

RECEIVED

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

## NEW MEXICO OIL CONSERVATION COMMISSION

ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>K-6227</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name --
2. Name of Operator <b>Pubco Petroleum Corporation</b>	8. Farm or Lease Name <b>Hope South State Com</b>
3. Address of Operator <b>P. O. Box 869, Albuquerque, New Mexico 87103</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>0</b> , <b>990</b> FEET FROM THE <b>South</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>5</b> TOWNSHIP <b>19S</b> RANGE <b>23E</b> NMPM.	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4005 GL</b>	12. County <b>Eddy</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☒  
CASING TEST AND CEMENT JOBS ☒  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded @ 7 P.M. 4/17/72. Ran 4 joints (175.00') 13-3/8", 72#/ft new limited service casing. Landed @ 165'. Cemented with 400 sacks, Class "C", 2% CaCl, 1/4 # Flocele/sack. Cement did not circulate. P.D. @ 8:50 P.M. 4/19/72. Filled to surface with 20 yards ready mix. WOC 18 hours. Tack-welded collars in four quadrants on bottom two joints. Use thread lock on bottom 3 joints.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles W. Sanders TITLE **Area Production Manager**

DATE **4/21/72**

APPROVED BY W. A. Gressett TITLE **Area Production Manager**

DATE **MAY 3 - 1972**

CONDITIONS OF APPROVAL, IF ANY: