

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O.C.C.
ALBUQUERQUE, OFFICE

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

L-1493

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator OVERLAND DRILLING & EXPLORATION LTD.	8. Farm or Lease Name Lowe State
3. Address of Operator Unknown Plantation apt. #13 Roswell N.M. 88201	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>1650</u> FEET FROM THE <u>N</u> LINE AND <u>330</u> FEET FROM THE <u>W</u> LINE, SECTION <u>15</u> TOWNSHIP <u>19S</u> RANGE <u>29E</u> N.M.P.M.	10. Field and Pool, or Wildcat <u>Wildcat San Andres</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well Plugged and Abandoned as follows: 4-10-79
TP 2870 8 3/8" - 300 - 75

- (1) Hole loaded w/mud laden fluid.
- (2) Set 35sx Plug @ 2,750'
- (3) Set 35 sx Plug @ 2,200'
- (4) Set 35 sx Plug @ 1,570'
- (5) Set 35 sx Plug @ 1,075'
- (6) Set 35 sx Plug @ 350' (Did not tag.)
- (7) Set 35 sx Plug @ 350' Tag @ 222'
- (8) Set 15 sx Plug @ Surface & 10 sx in cellar
- (9) Erect Marker
- (10) Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Barry C. Hobbs TITLE Manager-Hobbs Pipe & Supply DATE 6/8/79

APPROVED BY W.A. Gressett TITLE SUPERVISOR, DISTRICT II

DATE

JUN 12 1979

CONDITIONS OF APPROVAL, IF ANY: