

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

JUL 05 '88

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
L-4222

7. Unit Agreement Name

8. Farm or Lease Name
Eddy GZ State Com.

9. Well No.
1

10. Field and Pool, or Wildcat
Angell Ranch Atoka
Morrow

12. County
Eddy

SUNDRY NOTICES AND REPORTS ON WELLS **O.C.D.**
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER-

2. Name of Operator
Steve Sell ✓

3. Address of Operator
P. O. Box 5061, Midland, Texas 79704

4. Location of Well
UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM
THE East LINE, SECTION 12 TOWNSHIP 19S RANGE 27E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3521' Grd.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-16-88 Set CIBP at 8685'. Spot 35 sx. plug on top of CIBP. Tagged top of cement at 8280'. Spot 10 sx. plug 8280'-8180'.

6-20-88 Cut casing at 6650'.

6-21-88 Spot 40 sx. plug 6710-6532'. Tagged plug at 6532'. Spot 30 sx. plug at 4875-4775'. Spot 30 sx. plug 3430-3330'.

6-22-88 Set cement retainer at 2462' log depth. Squeeze with 42 sx. String out and spot 14 sx. on top of retainer. Clean up and prepare to complete San Andres zone. Witnessed by Mr. Robinson.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mike Williams TITLE Agent DATE 7-1-88

Original Signed By
Mike Williams
Oil & Gas Inspector

JUL 5 1988