

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-2537

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

South Taylor 13 Fed.

9. WELL NO.

#3

10. FIELD AND POOL, OR WILDCAT
Shugart, Seven Rivers, Queen

Grayburg, San Andres

11. SEC., T., R., OR BLM. AND
SURVEY OR AREA

31
Sec. 13, T-18S, R-18E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Harvey E. Yates Company

3. ADDRESS OF OPERATOR

P.O. Box 1933 Roswell, New Mexico 88202 ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

Unit letter O, 430' FSL & 1650' Fel

14. PERMIT NO.

30-015-25741

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3727.4' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-1-89 Set Rbp At 4150'

8-2-89 Abrasajet 2 cuts @ 3792'. Wash & acidize with 1000 gals 10% MSR-100.

8-4-89 Frac Cuts @ 3792' with 12,000 gals 30# x-link & 12,000#s 12-20 ottawa.

Frac Screened out with 7,800 gals fluid & 3,000#s sand in formation.

8-5-89 Put on production. SN @ 3857' & Anchor @ 3407'.

8-18-89 Pull RBP out of hole. GIH & set SN @ 4545' & Anchor @ 3573'. Put on prod.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Prod. Mgr./ Eng.

DATE

8-24-89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side