Form 9-3^1 (May 1963)				
		LITED STATES	SUBMIT IN TRILLICATE*	
	DEPART	MENT OF THE INTERI	OR verse side)	5. LEASE DESIGNATION AND SERIAL NO.
GEOLG		GEOLOGICAL SURVEY		LC-029392 B
SIIN	DRY NO	TICES AND REPORTSRE	MI WELLS COLLEGE	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this	form for prop	posals to drill or to deepen or plug be CATION FOR PERMIT—" for such pro-	ick to a different reservoir.	
1.	Use "APPLI	CATION FOR PERMIT— for such pr	oposats.)	7. UNIT AGREEMENT NAME
OIL V GAS		MΔI	R 31 '88 MAR 10 '88	
WELL & WELL 2. NAME OF OPERATOR	OTHER		12- 00 MAN 10 00	8. FARM OR LEASE NAME
Westall- M	lask 🗸	်	CD OCD	Hinkle "B" Federal
3. ADDRESS OF OPERATOR			BIA, OFFICEARTESIA, OFFICE	9. WELL NO.
P.O. Drawer 1477 Roswell, N.M. 88201 4. LOCATION OF WELL (Report location clearly and in accordance with any State				20
4. LOCATION OF WELL (R See also space 17 belo	eport location	clearly and in accordance with any	State requirements.*	10. FIELD AND POOL, OR WILDCAT
At surface				Shugart Y-SR ()-(-)
2310	' FSL an	nd 2310'FEL		SURVEY OR AREA
				Sec. 27, T18S, R31E
14. PERMIT NO.		15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
III I I I I I I I I I I I I I I I I I		3631GF		Eddy N.M.
	<u> </u>			
16.	Check A	Appropriate Box To Indicate N		
,	NOTICE OF INT	ENTION TO:	SUBSEC	UENT REPORT OF:
TEST WATER SHUT-0	FF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT		MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE		ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL		CHANGE PLANS	(Other)(Note: Report result	s of multiple completion on Well pletion Report and Log form.)
17. DESCRIBE PROPOSED OF proposed work. If nent to this work.)	well is dire	OPERATIONS (Clearly state all pertinent ctionally drilled, give subsurface locat	t details, and give pertinent dates ions and measured and true verti	s, including estimated date of starting any cal depths for all markers and zones perti
On 10-18-8	37 the fo	ollowing work was done:	:	
		_	:	
0n 10-18-8 8 5/8 - 45		_	:	
		_	•	
		_	:	
		_	•	
		_	:	
		_	:	
		_	•	
		_	•	
		_	•	
		_	•	
		_	•	
		_	•	
		_	•	
		_	•	
8 5/8 - 45	50' circu	ılated	•	
8 5/8 - 45	t the foregoin	slated		DATE
8 5/8 - 45 18. I hereby certify that SIGNED	t the foregoin	g is true and correct		DATE
8 5/8 - 45	t the foregoin	g is true and correct		DATE