

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP!  
(Other Instructions  
reverse side)

TE-  
re

Form approved  
Budget Bureau No. 1004-01-1  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 58143

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Cholla AGE Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat *morrow*

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Unit I, Sec. 3-T20S-R24E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different rock.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

105 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

2080' FSL & 660' FEL, NE/SE, Sec. 3-20S-34E

14. PERMIT NO.

API #30-015-26701

15. ELEVATIONS (Show whether DF, RT, GK, etc.)

3692.7' GR

O. C. D.  
ARTESIA, OFFICE

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spud well, set surface casing

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

17. DESCRIBE PROPOSED OR COMPLETED OPERATION (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Spudded 26" hole 8:30 AM 2-28-89 with Frank's Rathole. Set 25' of 20" conductor. Redi-mix to surface. Notified Dale Carpenter, BLM, Carlsbad, NM of spud. Resumed drilling 14-3/4" hole with rotary rig 8:30 PM 3-4-89. Lost circulation 48'. Drilled out with water. Worked stuck pipe at 88'. Ran 1". Washed 60' to bit at 88'. Pulled loose. Mixed LCM and regained circulation. Twisted off at 764'. Left bit and 1 drill collar in hole. WIH/w/overshot and caught fish. Ran 29 joints 9-5/8" 36# J-55 ST&C casing, set 1200'. Texas Pattern Notched guide shoe set 1200', insert float set 1158'. Cemented w/650 sx Pacesetter Lite, 1/2#/sx Celloseal, 5#/sx Gilsonite + 3% CaCl2 (yield 1.84, weight 12.7). Tailed in w/200 sx Class c + 2% CaCl2 (yield 1.32, weight 14.8). PD 4:15 PM 3-9-89. Bumped plug to 1000 psi, released pressure and float held okay. Circulated 50 sx cement to surface. WOC. Drilled out 11:15 AM 3-10-89. WOC 19 hrs. NU and tested to 1000 psi for 30 minutes, OK. Reduced hole to 8-3/4" and resumed drilling.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Supervisor

DATE 3-13-89

(This space for Federal or State office use)

APPROVED BY

TITLE

ACCEPTED FOR RECORD

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 24 1989

\*See Instructions on Reverse Side

SJS  
CARLSBAD, NEW MEXICO