

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Yates Queen	2657'	2875'	Sand and Dolomite
	3303'	3881'	Sand and Dolomite
		DEPTH	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)
		3606'-3631'	1000 gals 15% NeFe acid + 24 BS.
			10,000 gals 30# X-Link gel + 32,000# 20/40 Ottawa sd + 4,000# 20/40 RC sd.
		3754'-3844'	2500 gals 15% Ne Fe Acid + 50 BS
			20,500 gals 30# X-Link gel + 58,500# 20/40 sd + 16,000# 16/30 RC sd.

38.

GEOLOGIC MARKERS

NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH
Rustler	750'	
Salt	953'	
Yates	2657'	
Queen	3303'	
Grayburg	3881'	