

--	--	--	--	--	--	--	--	--	--

# LOG OF OIL OR GAS WELL

LOCATE WELL CORRECTLY

Company **Schuster & Messinger** Address **P. O. Box 415 Artesia, New Mexico**  
 Lessor or Tract \_\_\_\_\_ Field **Wildcat** State **New Mexico**  
 Well No. **1** Sec. **15** T. **21S** R. **28E** Meridian **N10W** County **Eddy**  
 Location **1980** ft. **SW** of **N** Line and **W** of **E** Line of **Sec 15** Elevation \_\_\_\_\_  
(Derrick floor relative to sea level)

The information given herewith is a complete and correct record of the well and all work done thereon so far as can be determined from all available records.

Date **August 10, 1943**

Signed **C. S. Messinger**  
 Title **Partner**

The summary on this page is for the condition of the well at above date.

Commenced drilling **April 27**, 19**42** Finished drilling **July 6, 1943**, 19**43**

## OIL OR GAS SANDS OR ZONES

(Denote gas by G)  
 No. 1, from **2615** to **2626**  
 No. 2, from **26626** to **26644**  
 No. 3, from \_\_\_\_\_ to \_\_\_\_\_  
 No. 4, from \_\_\_\_\_ to **2643**  
 No. 5, from \_\_\_\_\_ to \_\_\_\_\_  
 No. 6, from \_\_\_\_\_ to **L. G. Snow**

## IMPORTANT WATER SANDS

No. 1, from \_\_\_\_\_ to \_\_\_\_\_  
 No. 2, from \_\_\_\_\_ to \_\_\_\_\_  
 No. 3, from \_\_\_\_\_ to \_\_\_\_\_  
 No. 4, from \_\_\_\_\_ to \_\_\_\_\_

## CASING RECORD

Size casing	Weight per foot	Threads per inch	Make	Amount	Kind of shoe	Cut and pulled from	Perforated		Purpose
							From—	To—	
<b>8 1/2</b>	<b>32</b>	<b>8</b>	<b>Stand</b>	<b>397</b>	<b>Reg</b>				<b>Salt String</b>
<b>8 1/2</b>	<b>32</b>	<b>8</b>	<b>Stand</b>	<b>397</b>	<b>Reg</b>				<b>Salt String</b>

## MUDDING AND CEMENTING RECORD

Size casing	Where set	Number sacks of cement	Method used	Mud gravity	Amount of mud used
<b>8 1/2</b>	<b>397</b>	<b>50</b>	<b>Caliburton</b>	<b>28</b>	<b>3 tons</b>
<b>7</b>	<b>2980</b>	<b>100</b>	<b>#</b>	<b>28</b>	<b>4</b>

## PLUGS AND ADAPTERS

Heaving plug—Material \_\_\_\_\_ Length \_\_\_\_\_ Depth set \_\_\_\_\_  
 Adapters—Material \_\_\_\_\_ Size \_\_\_\_\_

## SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
<b>6</b>	<b>2"</b>	<b>Nitroglycerin</b>	<b>20</b>	<b>6-22</b>	<b>2626-2644</b>	<b>2649</b>

## TOOLS USED

Rotary tools were used from \_\_\_\_\_ feet to \_\_\_\_\_ feet, and from \_\_\_\_\_ feet to \_\_\_\_\_ feet  
 Cable tools were used from **1** feet to **2649** feet, and from \_\_\_\_\_ feet to \_\_\_\_\_ feet

**July 10, 1943**

## DATES

**July 10, 1943**

The production for the first 24 hours was **25**

Put to producing **July 10, 1943**, 19**43**

FOLD MARK