

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Mr. **Staley,** Roswell, N. Mex., June 25, 1929
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon Sullivan-Rundle Well
No. 1 in NW 1/4 SW 1/4 of Sec. 19 of ~~Sec.~~ 20 S., R 30E.
N. M. P. M., Getty Oil Field, Eddy County.
We plan to commence work on _____, 19____.

The reasons for wishing to abandon the well are as follows:

Geologically low and dry

The present condition of the well is as follows:

Plugged

The work which we propose to do in abandoning the well is as follows:

To meet requirements of State Geological Dept.

Approved June 27 1929

Except as follows:

Sincerely yours,

Sullivan-Rundle

Company or Operator.

By Bruce Sullivan

Position Agent,

Send communications regarding this well to

Name Bruce Sullivan

Address Santa Fe, New Mexico.

A. L. Haller
State Geologist or Oil and Gas Inspector.