Submit 3 Copies to Appropriate District Office

Energy,

Form	C-103	
Revise	d 1-1-89)

State of New Mexico	
, Minerals and Natural Resources Department	

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088

30-015-10414 5. Indicate Type of Lease STATE X FEE L

WELL API NO.

1000 Rio Brazos Rd., Aztec, NM 87410	VA-636			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMAT (FORM C-101) FOR SUCH PROPOSALS)	JG BACK TO A 7. Lease Name or Unit Agreement Name			
1. Type of Well:	315 %			
OIL GAS WELL X OTHER	Archimedes ARE State Com			
2. Name of Operator				
THE PROPERTY OF THE CONTRACTOR	1			
3. Address of Operator	9. Pool name or Wildcat Indian Basin Morrow, East			
105 South 4th St., Mrtesta, M. 65215	Indian Basin Morrow, East			
Unit Letter J : 1650 Feet From The South	Line and 1980 Feet From The East Line			
Section 18 Township 21S Range	24E NMPM Eddy County			
Section 1.8 Township 2.15 Kange (1) 10. Elevation (Show whether DF, RKI)				
//////////////////////////////////////	XIIIIIIIIIIIX			
11. Check Appropriate Box to Indicate Nature	e of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:			
	EDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COM	MENCE DRILLING OPNS. PLUG AND ABANDONMENT			
TOLE OF THE PERSON OF THE PERS	NG TEST AND CEMENT JOB			
OTHER:	ER: Perforate & acidize X			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pwork) SEE RULE 1103.				
7 22 07 Finished TIH with 2-7/8" L-80 tubing W	with bit and scraper. Tagged at 9691'.			
Percence girculated 100 bbls. Circulate hole via tubing with 2% KCL water. Poon. Rigged				
up wireline. TIH with logging tools and ran CB	L log. TOOH with logging tools and			
rigged down wireline.	ng guns and perforated 9521-9599' w/162			
7-23-97 - Rigged up wireline. TIH with 4" casing guns and perforated 9521-9599' w/162 .42" holes as follows: 9521-9530', 9551-9555', 9577-9586' and 9594-9599' (6 SPF - Morrow).				
moon with againg oung and rigged down wireling.	TIH with packer and kbr. Set kbr at			
overt probled tubing with 200 gallons acid.	Snot 200 gailons acid at 9025 . Sec			
Broke down perforations 95//-	9599. Moved RDP to 9504 and packer to			
05271 Proke down perforations 9551-9555'. Mo	ved RBP to 953/ and packer to 9409			
Broke down perforations 9521-9530'. NOTE: Pum	ped 3 bbls into each set of periorations			
Attempted to move RBP back to 9655'. Would not	go down hole. Took, and faid down packer			
and RBP. TIH with packer with on/off tool and	2.25" profile. Set packer at 9409.			
Nippled down BOP and nippled up tree. Swabbed.	COMMINGED ON NEVE DAGE.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	CONTINUED ON NEXT PAGE:			
SIGNATURE JUSTEY THE O	perations Technician DATE Aug. 4, 1997			
TYPEOR PRINT NAME Rusty Klein	TELEPHONE NO. 505/748-1471			
(This space for State Use)	Allo o toss			
ORIGINAL SIGNED BY TIM W. GUM	AUG 8 1997			