

6. RU HOWCO. LOAD BACKSIDE W/2% KCL WTR & TRAP 500 PSI. SET CSG POP OFF VALVE @ 1000 PSI. ACDZ PERFS (7413-7488) W/3200 GALS 15% FE HCL FOAMED W/N₂ TO 75% QUALITY @ 3 BPM
MAX PRESSURE = 3500 PSI AS FOLLOWS:

- A. 200 GALS 15% FE HCL
- B. 5000 GALS 75% FOAMED 15% FE HCL
- C. 2000 GALS 75% FOAMED 15% FE HCL W/ 1#/GAL TBA-110 (RS)
- D. 5000 GALS 75% FOAMED 15% FE HCL
- E. FLUSH W/±25,000 SCF N₂
- F. OBTAIN ISIP, 5 MIN, 10 MIN, & 15 MIN SIP
- G. OPEN WELL FLOW TO FRAC TANK REC LOAD
- H. SWITCH WELL TO PROD UNIT

SUMMARY: TOTALS 3200 GALS 15% FE HCL
 255,000 SCF N₂ (INCLUDING COOLDOWN)
 2000 LBS. TBA-110 ROCK SALT

ADDITIVES: 15% FE HCL - 5 GALS/M PEN - 5
 - 2 GALS/M HAI-65
 ROCK SALT - 1 LB/GAL IN 1000 GALLONS FOAM

7. RR