MM OIL CONS. OMMISSED

Drawer DD Artesia, NM 88210 FORM APPROVED

Form 2160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.

W 0/28854

Type of Well Well X Well Other Tame of Operator Att F.R	7. If Unit or CA. Agreement Designation Burton Flat Deep Unit
SUBMIT IN TRIPLICATE	7. If Unit or CA. Agreement Designation Burton Flat Deep Unit
SUBMIT IN TRIPLICATE Spe of Well Well X Well Other Tame of Operator	Rurton Flat Deen Unit
pe or Well Well X Well Other ame of Operator At At A	Rurton Flat Deen Unit
pe of Well On	
Well X Well Other The of Operator The Attribute Attrib	No. 14-08-0001-12391
ame of Operator	8. Weil Name and No.
DUD Described American Inc. 1//4. HILA. 1/4 Dec.	9 API Well No.
100	API Well No.
duress and Telephone No.	10. Field and Pool, or Exploratory Area
584/ San Felipe, Suite 5000, Louiston, 1	Undesignated Bone Spri
ocation of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, State
1930' FNL, 1980' FWL	N. V. vida
Sec. 27-T20S-R28E	Eddy County, New Mexic
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOT	TICE, REPORT, OR OTHER DATA
	PE OF ACTION
X. Notice of Intent	Change of Plans
Recompletion	New Construction
Subsequent Report Plugging Back	Non-Rouune Fracturing
Casing Repair	Water Shut-Off
Final Abandonment Notice	Conversion to Injection To abandon Dispose Water
Other Temporari	Note: Report results of multiple completion on well
Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertunent dates, including estimated for all markers and zones pertunent to this wo	Completion or Recompletion Report and Log (orm.)
Existing perforations 5321' to 5363'. Propose to temporarily abandon by setting CIBP @ 5300' planned work in the unit for recompletion in the uphole be placed on top of CIBP and all down hole production excasing will be filled with corrosion inhibited fluid and 30 minutes.	quipment will be removed. Producted pressure tested to 500 psi for
	COURT 6 MAN 1993

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any talse, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

Conditions of Approval

According to 43 CFR 3162.3-4-c, "No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits a subsequent Sundry Notice requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test chart,
- And explains why such a well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnessed by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to θ LM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.