

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26586
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1673
7. Lease Name or Unit Agreement Name Lost Tank AIS State
8. Well No. 3
9. Pool name or Wildcat Wildcat Canyon
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3564' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471
3. Address of Operator 105 South 4th St., Artesia, New Mexico 88210	4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 36 Township 21S Range 31E NMPM Eddy County

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Frac well ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-12-91. RUPU. Unseat pump. TOH with rods, tubing, pump. TIH with packer. set 7000'.  
Frac'd perfs 7055-84' (via 2-7/8" tubing) with 7500 gals 40# x-link gel w/20000# 20/40  
sand. Released packer, TOH. TIH w/packer and RBP, set RBP 7000', and tested. Frac'd  
perfs 6783-6810' w/7500 gals 40# x-link gel + 20000# 20/40 sand. TOH with packer.  
Unseat RBP and TOH. TIH with pumping equipment. Hung well on pump 3-14-91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-18-91  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAR 21 1991

CONDITIONS OF APPROVAL, IF ANY: