

SURFACE USE PROGRAM

HOC FEDERAL GAS COM NO. 2 - Cont'd PAGE 3

- C) The reserve pit will be fenced on three sides with barbed wire during drilling and completion operations. The pit and those areas not essential to production facilities will be reclaimed and seeded per BLM requirements.

10) Plans for Reclamation of Surface:

- A) After drilling and/or completion operations cease, restoration of the location will start in a timely manner. All equipment and other material not needed for further operations will be removed. The location will be cleared to leave the wellsite in as aesthetically pleasing condition as possible.
- B) The reserve pit will be completely fenced with a protective net placed over the pit to protect wildlife while the drilling fluids are allowed to evaporate. The pit will then be leveled and contoured to conform to the surrounding area. Revegetation will be implemented if the area is not required for surface facilities.
- C) If the proposed well is non-productive, the pad and road area will be recontoured to match the existing terrain. All rehabilitation and/or vegetation requirements of the BLM will be complied with as expeditiously as possible.

11) Other Information:

A cultural resources survey on the area was completed on December 13, 1991 by New Mexico Archaeological Services, Inc. A copy of the report is attached.

12) Operators Representative

Apache field representative for contact regarding compliance with the Surface Use Program:

Jim Ellison, Production Foreman  
Box 848  
Wink, Texas 79789  
Office: 915-527-3311  
Home: 505-395-2266