Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

C151

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980 Hobbs NM 88240

DIT CON?	EKVAIIL	NOTATON
	P.O. Box 208	88
Canta Ea	Manu Marrian	07504 2000

ELL API NO.	
30-015-28531	
. Indicate Type of Lease	
STATE	FEE X

F.O. Box 1700, 110001, 14M1 86240	P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			30-015-28531 5. Indicate Type of Lease
DISTRICT III			STATE FEE K
1000 Rio Brazos Rd., Azzec, NM 87410		A	6. State Oil & Gas Lease No.
SUNDRY NOTICES	AND REPORTS ON WEI	LLS	
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR	USE "APPLICATION FOR PE	HOR PLUG BACK TO A PRINTY	7. Lease Name or Unit Agreement Name
(FORM C-101) F	OR SUCH PROPOSALS.)	3.5	_
OR. X WELL X	OTHER		Mojave AJY Com
2. Name of Operator V YATES PETROLEUM CORPORATIO	N		8. Well No.
3. Address of Operator	· · · · · · · · · · · · · · · · · · ·		9. Pool name or Wildcat
105 South 4th St., Artesia	, NM 88210		Dagger Draw Upper Penn, South
4. Well Location	01		
Unit Letter O: 660 F	ect From The South	Line and1980	Feet From The East Line
Section 35 Tr	ownship 20½ South Ra	uge 23 East	NMPM Eddy County
<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	NMPM Eddy County
		GR	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
NOTICE OF INTENT	opriate Box to Indicate I		
NOTICE OF INTENT	ION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON (CHANGE PLANS	COMMENCE DRILLING	
PULL OR ALTER CASING		CASING TEST AND CE	<u> </u>
OTHER:		OTHER: Add perf	s in Canyon & acidize X
12. Describe Proposed or Completed Operations (Completed Operation	learly state all pertinent details, an	l d give pertinent dates, includ	ling estimated date of starting any proposed
work) SEE RULE 1103. 9-8-99 - Moved in and rigg	ed up pulling unit	TOOU tideb wa	da
9-9-99 - Pumped 40 bbls 2%	KCL water. Nippl	ed up ROP. Rel	eased tubing anchor. TOOH
with tubing. TIH with bit	, scraper and tubi	ng to 7878'. To	OOH with tubing, scraper and
bit. Shut down.			
9-10-99 - Rigged up wireli	ne. TIH with 4" c	asing guns and	perforated 7564-7650' w/19
.42" holes as follows: 75	64, 65, 66, 80, 81	, 88, 89, 90, 7	600, 01, 02, 03, 16, 17, 18,
4/, 48, 49 & 7650' (1 SPF	- Canyon). TOOH w	ith casing guns	and rigged down wireline.
Till with packer and RBP.	Straddled perforat	ions 7714-7731'	. Acidized with 2000 gallons
20% gelled Dagger Draw HCL	acid. Moved tool	s and straddled	perforations 7564-7650'.
Acidized with 15000 gallon	s 20% gelled Dagge	r Draw HCL acid	and ball sealers. Moved
gelled Dagger Draw MCI agd	d Moved tools	Acidized perio	orations with 2000 gallons 20%
gelled Dagger Draw HCL aci	ing pooker and PP	d straddied all	perforations. Swabbing. 11 to production department.
Open perforations: 7458-7	774' (Canyon)	r. Released we	ir to production department.
I hereby certify that the information above is took find com		edia.	
SIGNATURE TUSTUS TUSTUS	т.	Operations Te	echnician Sept. 24, 1999
TYPE OR PRINT NAME Rusty Klein			ТЕГЕРНОМЕ NO. 505/748-147
(This space for State Use)	(1) (4,)	Diti-	Sugariani

APPROVED BY-