

BOGLE FLATS UNIT 5 #1106/28/95

TMD: 2970 TVD: 2970 PBTMD: 0 PBTVD: 0
05:00 11:30 02A A DRLG. 2285' - 2504'
11:30 11:45 10A SURVEY AT 2462' - 1/4 DEG.
11:45 03:45 02A A DRLG. 2504' - 2941'
03:45 04:00 10A SURVEY AT 2900' - 1/2 DEG.
04:00 05:00 02A A DRLG. 2941' - 2970. ART: DRILLING AT 25 FPH
W/ NO TROUBLE

06/29/95

TMD: 3536 TVD: 3536 PBTMD: 0 PBTVD: 0
05:00 20:45 02A A DRLG. 2970' - 3379'
20:45 21:00 10A SURVEY AT 3338 - 3/4 DEG.
21:00 05:00 02A A DRLG. 3379' - 3536'. ART: DRILLING AT 20 FPH
W/ NO TROUBLE

06/30/95

TMD: 4080 TVD: 4080 PBTMD: 0 PBTVD: 0
05:00 17:00 02A A DRLG. 3536' - 3818'
17:00 17:15 10A SURVEY AT 3777' - 1/4 DEG.
17:15 05:00 02A A DRLG. 3818' - 4080'. ART: DRILLING 22 FPH W/
NO TROUBLE.

07/01/95

TMD: 4585 TVD: 4585 PBTMD: 0 PBTVD: 0
05:00 13:30 02A A DRLG. 4080' - 4259'
13:30 14:00 10A SURVEY AT 4217' - 1 1/4 DEG.
14:00 04:00 02A A DRLG. 4259' - 4569'
04:00 04:15 10A SURVEY AT 4548' - 3/4 DEG.
04:15 05:00 02A A DRLG 4569' - 4585'. ART: DRILLING AT 20 FPH
W/ NO TROUBLE

07/02/95

TMD: 5125 TVD: 5125 PBTMD: 0 PBTVD: 0
05:00 02:00 02A A DRLG. 4585' - 5069'
02:00 02:15 10A SURVEY AT 5028' - 1 1/2 DEG.
02:15 05:00 02A A DRLG. 5069' - 5125'. ART: DRILLING 20 FPH W/
NO TROUBLE

07/03/95

TMD: 5635 TVD: 5635 PBTMD: 0 PBTVD: 0
05:00 23:00 02A A DRLG. 5125' - 5538'
23:00 23:15 10A SURVEY AT 5523' - 2 DEG.
23:15 02:00 02A A DRLG. 5538' - 5635'. W/ NO TROUBLE
02:00 05:00 06A A TRIP FOR BIT # 3