State of New Mexico inerals and Natural Resources Department Energ

F	om	C-	103	
F	Revis	ed	1-1	-

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 **OIL CONSERVATION DIVISION** 2040 Pacheco St.

	CISI
WELL API NO.	

89

P.O. BOX 1900, 110003, 14141 002-40		2040 Pacheco S Santa Fe, NM			30-015-29448		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210		Santa re, INW	- 67303 - (1,2,4,1,1,1)		sIndicate Type of Lease	STATE	FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 8741	10		*	2.2	State Oil & Gas Lease	No.	
(DO NOT USE THIS FORM FO	OR PROPOSALS TO	REPORTS ON W DRILL OR TO DEEP "APPLICATION FOR UCH PROPOSALS.)	BERWHELL BAC	ск то х	7Lease Name or Unit A Como Fee	greement Name	
Type of Well: OIL GAS WELL WELL		OTHER		. ``.			
² Name of Operator Marbob Energy Corporation					«Well No. 1		
Address of Operator P.O.Box 227, Artesia, NM 8					Pool name or Wildcat Morrow		
4Well Location Unit Letter F		ne North	Line and	1650	Feet From The	West	Line
Section	17 Townsh	ip 21S	Range	25E	NMPM	Eddy	County
	in the state of the country of the c	Elevation (Show whether 403'Gr	DF, RKB, RT, GR, e	etc.)			
11 Che	eck Appropriate	Box to Indicate	Nature of No	tice, Re	port, or Other Da	ata	

SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PLUG AND ABANDON **ALTERING CASING** REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ANBANDONMENT COMMENCE DRILLING OPNS. CHANGE PLANS **TEMPORARILY ABANDON** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Notify OCD 24hrs before starting 1. PÓH w/ 296jts. 2 3/8 & 5 1/2 ASI 10K Pkr. 2. Set CIBP @ 92000 w/ 35' cmt on top /0/59 3. Cut & pull 5 1/2 @ 8400' 4. RIH spot 100' plug 50' in & out stub Tag Plug

5. Spot 100' plug @ 7354 to 7254

6. Spot 100' plug @ 3680 to 3580

7. Spot 100' plug 50' in & out 8 5/8 shoe @1450

7. Spot 100' plug 50' in & out 8 5/8 shoe @1450

7. Spot 100' plug 50' in & out 8 5/8 shoe @1450

7. Spot 100' plug 50' in & out 8 5/8 shoe @1450

7. Spot 100' plug 50' in & out 8 5/8 shoe @1450

7. Spot 100' plug 50' in & out 8 5/8 shoe @1450

8. Spot 35' plug @ surface Install Dry hole marker

A Place 9.8 mud between All plass

I hereby certify that the information above is true and complete to	the best of my knowledge and belief.	
SIGNATURE Wayne Brooks	TITLE Agent	DATE 03-08-01
TYPE OR PRINT NAME Wayne Brooks		тецерноме мо. 915 5807161
(This space for State Use)	1.011	30 lan
APPROVED BY	Sield Sep &	DATE Clingost Illo