

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-31003
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-3576
7. Lease Name or Unit Agreement Name	Aviette ALK State Com
8. Well No.	2
9. Pool name or Wildcat	Burton Flat Morrow

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210

4. Well Location Unit Letter 0 : 860 Feet From The South Line and 1980 Feet From The East Line Section 17 Township 21S Range 27E NMPM Eddy County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3248' GR
---	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate, acidize & squeeze <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-16-17-2000 - Cleaned location and set anchors. Moved in and rigged up pulling unit.
7-18-2000 - TIH with bit, scraper and tubing and tagged PBTD at 11650'. Pickled tubing with 1000 gallons 15% NEFE acid. Loaded hole with 7% Super fluid. Started TOOH.
7-19-2000 - Finished TOOH with bit, scraper and tubing. Rigged up wireline. TIH with logging tools and ran GR/CBL/CCL log. TOOH with logging tools. TIH with 4" expendable guns and perforated 11594-11598' w/16 .42" holes (4 SPF - Morrow). TOOH with guns and rigged down wireline. TIH with packer with on/off tool, 1.81" F profile and 364 joints of tubing to 11546'. Set packer and tested to 1000 psi. Nippled down BOP and nipped up wellhead. Shut down for night.
7-20-2000 - Acidized perforations 11594-11598' (Morrow) with 1500 gallons of 7-1/2% MSA acid and 1000 scf N2. Flushed with 7% Super fluid and N2. Opened well and bled well down. Flowed well back. Shut well in.
7-21-2000 - Swabbed & flow tested. Shut well in.
7-22-24-2000 - Flow tested. Shut well in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE Sept. 20, 2000

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-147

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

NOV 03 2000

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: