Form 3160-5 (November 1994)

'D STATES DEPARTML... OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

14 '141' A		DIVISION B No. 1004-0135 Expures July 31, 1996
811 S. 1st	Sti	eese Senal No.

Do not use this form for proposals to drill or to re-enter and testa, NM 88210-29 6. If Indian, A abandoned well. Use Form 3160-3 (APD) for such proposals. 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side Type of Well Oil Well Gas Well Other 8. Well Name and No. Dxx Penny Loafer Tederal # Name of Operator OXY USA WTP Limited Partnership API Well No. 192463 30-015-31453 Phone No. (include area code) Address 10. Field and Pool, or Exploratory Area P.O. Box 50250 Midland, TX 79710 915-685-5717 Indian Basin Morrow, W. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 1350 FNL 930 FEL SENE (H) Sec 23 TZIS RZZE Eddy NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION ■ Water Shut-Off Deepen Deepen Production (Start/Resume) □ Acidize Notice of Intent Well Integrity Fracture Treat ☐ Reclamation Alter Casing De Other Span , SET Recomplete **New Construction** Subsequent Report Casing Repair Plug and Abandon Temporarily Abandon Change Plans Final Abandonment Notice Plug Back Water Disposal Convert to Injection Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) See Other Side DRIG. SGD.) DAVID R. GLASS BLM I hereby certify that the foregoing is true and correct Name (Printed/Typed) David Stewart Regulatory Analyst Date Signature zls loi THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Date Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ATTACHMENT 3160-5 OXY USA INC. OXY PENNY LOAFER FEDERAL #1 SEC 23 T21S R22E EDDY COUNTY, NM

NOTIFIED BLM \$\frac{1}{2}\)/20/00 OF SPUD. MIRU UTI \$\frac{1}{3}\)07, SPUD WELL @ 2300hrs MST 12/20/00. DRILL 17-1/2" HOLE TO 378' & LOST RETURNS, M&P LCM SWEEPS W/O SUCCESS, DRY DRILL TO TD @ 400', 12/21/00, PUMP SWEEP. RIH W/ 13-3/8" 48# H40 CSG, SET @ 400'. M&P 200sx CL H W/ 10\frac{1}{8}\) BWOCA-10B + 10\# GILSONITE + .25\#/sx CELLOFLAKES + 1\frac{1}{8}\) Cacl2 FOLLOWED BY 185sx 65:35 C/POZ W/ 6\frac{1}{8}\) BENTONITE + .25\#/sx CELLOFLAKES + 2\frac{1}{8}\) Cacl2 FOLLOWED BY 200sx CL C W/ 2\frac{1}{8}\) Cacl2, DISP W/ FW, PLUG DOWN 12/21/00, HAD INTERMITTENT CIRC DURING JOB, CIRC 36sx CMT TO PIT, WOC-6hrs. BLM NOTIFIED, GENE HUNT WITNESSED CMT JOB & TAG. RIH W/ 1", TAG CMT @ 25', TOP OUT W/ READY MIX. CUT OFF CASING, WELD ON WELL HEAD, TEST TO 500\#, OK. NU BOP & TEST BOP & CASING TO 500\#, OK. TEST PIPE RAMS & HYDRIL TO 500\#, OK. RIH & TAG, DRILL OUT & DRILL AHEAD 12/22/00.

DRILL 11" HOLE TO TD @ 2035' 12/26/00, RAN FLUID CALIPER, PUMP SWEEP. RIH W/8-5/8" 32# K55 CSG & SET @ 2035'. M&P 100sx CL H W/ 10% HNB + 10# GILSONITE + .25#/sx CELLOFLAKES + 1% CaCl2 FOLLOWED BY M&P 405sx 65:35 C/POZ W/ 6% BENTONITE + 2% CaCl2 + 5#/sx GILSONITE FOLLOWED BY 200sx CL C W/ 2% CaCl2 DISP/FW, PLUG DOWN 12/27/00, CIRC 199sx CMT TO PIT, WOC-4hrs. BLM NOTIFIED CATHY WITNESSED. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL, MUD LINES, & CASING TO 2500#, BLM NOTIFIED OF BOP TEST, DID NOT WITNESS. TOTAL WOC-12hrs. RIH & TAG, DO CMT, TEST, DRILL AHEAD 12/28/00.

DRILL 7-7/8" HOLE TO TD @ 9370', 1/20/01, PUMP SWEEP & CHC. RIH W/ OPEN HOLE LOGS, POOH. RIH W/ 5-1/2" 17# P110 CSG & SET @ 9370'. M&P 1100sx 61/15/11-C/POZ/CSE W/ .5% FL-25 + .5% FL-52 + 8#/sx GILSONITE FOLLOWED BY 100sx CL C CMT W/ .7% FL-25, DISP W/ KCLW, PLUG DOWN 1/23/01. CEMENT DID NOT CIRCULATE, CALC TOC-4500'. BLM NOTIFIED BUT DID NOT WITNESS. ND BOP, SET SLIPS, CUT OFF CSG, NUWH & JET CLEAN PITS, REL RIG @ 0300hrs MST 1/23/01. SI WOCU.

