

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-22277

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Martin

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER ☐

2. Name of Operator

Meteor Developments, Inc. ✓

8. Well No.

#5

3. Address of Operator

511 16th Street, Suite 400, Denver, CO 80202

9. Pool name or Wildcat

Carlsbad S, Cherry Canyon Sand

4. Well Location

Unit Letter L : 2210 Feet From The South Line and 990 Feet From The West Line

Section 20

Township 22-South

Range 27-East

Line NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3140-G.L. & 3150-K.B.

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

H.I.R., Pull rods & pump, Tag P.B.T.D. w/2-3/8 tbg, P.O.O.H. w/tbg, R.U.B.O.P. perf'd existing pay zone L. Cherry Canyon Sand @ 3270-72; 3279-86; 3290-3300 w/1 JPF & perf'd U. Cherry Canyon Sand @ 2686-94; 2699-2711; 2714-24 w/2 JPF R.I.H. w/ret. B.P. & Ret. packer on 2-3/8" tbg. Set B.P. @ 3320'± & set ret packer @ 3250'±. Acidize L. Cherry Canyon Sand perf's w/3000 gals 15% HCl w/additives. Flush acid to bottom perf. w/produced water. Release packer & go down & pick up Ret B.P. and move B.P. to 2750 ± ft and set. Pull packer up to 2650± ft and set. Acidize U. Cherry Canyon Sand perf's w/5000 gals of 15% HCl acid w/additives. Flush acid to bottom perf at 2724 ft. Release packer and pick up ret B.P. @3320 P.O.O. H. w/tbg & packer & B.P. R.I.H. w/1jt of 2-3/8" mud anchor, S.N., tbg anchor, 2-3/8" tbg. Set tbg tail inlet at 3340 ft. Prepare to swab acid load back and when fluid has cleaned up, R.I.H. w/pump & rods & place back into production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Bruce M. Patterson

TITLE

Vice-President-Engineering & Operations

DATE *1-25-93*

TYPE OR PRINT NAME

Bruce M. Patterson - Vice Pres. Engineering & Operations

TELEPHONE NO. *303-572-1135*

(This space for State Use)

APPROVED BY

Mike Williams

TITLE

SUPERVISOR, DISTRICT II

DATE

JAN 29 1993

CONDITIONS OF APPROVAL, IF ANY: