

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-23317
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	L-4502
7. Lease Name or Unit Agreement Name	Little Bear St. Unit
8. Well No.	2
9. Pool name or Wildcat	Undes. Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Siete Oil and Gas Corporation ✓
3. Address of Operator P.O. Box 2523, Roswell, NM 88202-2523	4. Well Location Unit Letter <u>E</u> : <u>2030</u> Feet From The <u>North</u> Line and <u>1085</u> Feet From The <u>West</u> Line Section <u>18</u> Township <u>24S</u> Range <u>25E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4360' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/21/93 TIH w/CIBP & set @ 5125', set 4 sxs cmt on top of CIBP, cut 5½" csg @ 2870', TIH to 2960' & set plug w/35 sxs "C", 4% CaCl, tag T/plug @ 2833', SION.

4/22/93 Set 2nd plug @ 2140'-2040' w/25 sxs "C", set 3rd plug @ 1310'-1210' w/25 sxs "C", set 4th plug @ 350'-250' w/25 sxs "C", TOH, set surface plug @ 30' w/15 sxs "C", RD, erect dry hole marker.

Part ID-2
5-21-93
P+H

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cathy Batley-Seely TITLE Regulatory Specialist DATE 5/11/93
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY RS TITLE _____ DATE 6-20-93
CONDITIONS OF APPROVAL IF ANY: _____