

NO. OF COPIES RECEIVED	
DISTRIBUTION	
DATE & TIME	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

SEP 14 1981

O. C. D.

ARTESIA, OFFICE

14. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
15. State Oil & Gas Lease No. L-5386

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-103) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator CITIES SERVICE COMPANY ✓
3. Address of Operator P. O. Box 1919 Midland, Texas 79702
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 22S RANGE 27E N.M.P.M.

7. Unit Agreement Name
8. Farm or Lease Name STATE DR
9. Well No. 1
10. Field and Pool, or Subset Und. Herradura Bend. Del
12. County Eddy

15. Elevation (Show whether DF, RT, GR, etc.) 3074.9 GR
--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T. D. 2605. Open Hole 346'-2605'. This well was plugged & abandoned in the following manner: RIH w/83 joint of 2-7/8" tbg. tagged T.D. @ 2604'. Circulated hole w/mud laden fluid.

1. Spotted 35 sx cement plug @ approx. 2604'-2504'.
2. POOH and lay down tbg. to 2377'. Spotted 35 sx of class C neat, cement plug to approx. 2377'-2277', across top of Delaware Ls.
3. Pulled tbg to 1285' & spotted 35 sx plug. Tagged plug @ 1140', across top of Salt @ 1127'.
4. Pulled tbg to 402' & spotted 35 sx plug. Spotted 35 sx plug approx. 402-302 half in-half out of 8-5/8" casing shoe @ 349', tagged plug @ 346'.
5. Laid down remaining tbg. dump 10 sx plug in top of casing.
6. Installed 4" Dry hole marker. Rig Down Unit. Will clean location later.

[Handwritten signature/initials]

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BY *Elmer Stantz* TITLE Reg. Oper. Mgr.-Prod. DATE 9-8-81

CO BY _____ TITLE _____ DATE _____
SIGNATURES OF APPROVAL, IF ANY: