State of New Mexico Form C-103 Submit 3 Copies Minerals and Natural Resources Department Revised 1-1-89 to Appropriate District Office OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs, NM 88240 WELL API NO. P.O. Box 2088 30-015-26974 Santa Fe, New Mexico 87504-2088 DISTRICT II 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATE FEE 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 V-2597 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: WELL X WELL Flora AKF State OTHER 2. Name of Operator 8. Well No. YATES PETROLEUM CORPORATION 9. Pool name or Wildcat 3. Address of Operator 105 South 4th St., Artesia, NM Lost Tank Delaware 4. Well Location K . 1980 Feet From The South Line Feet From The West Line and Unit Letter __ 1995_{IMPM} County **22S** Range Township Section 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3<u>528 GR</u> Check Appropriate Box to Indicate Wature of Notice, Report, or Other Data 11. DISTSUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: **ALTERING CASING** REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **TEMPORARILY ABANDON** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: Production casing & cement X OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. TD 8322'. Reached TD at 9:30 AM 3-28-95. Ran 201 joints of 5-1/2" 17# & 15.5# casing as follows: 38 joints of 5-1/2" 17# 8rd J-55 LT&C (1536.61'); 143 joints of 5-1/2" 15.5# 8rd J-55 LT&C (5983.08') and 20 joints of 5-1/2" 17# 8rd J-55 LT&C (811.27') (Total 8330.96') of casing set at 8322'. 1-float shoe set at 8322'. Float collar set at 8277'. DV tool set at 6287'. Cemented in two stages as follows: Stage 1: 500 gallons WMW-1 and 500 gallons surebond ahead of 350 sacks Super Modified "C", .4% CF-2, .3% CF-14, 5% salt and 8#/sack hiseal (yield 1.72, weight 13.0). PD 11:45 AM 3-29-95. Bumped plug to 1500 psi for 5 minutes. Circulated 81 sacks. Circulated through DV tool for 3 hours. Stage 2: 400 sacks Pacesetter Lite "C", 5#/sack salt, 5#/sack gilsonite and 1/4#/sack celloseal (yield 1.98, weight 12.5). Tailed in with 100 sacks "C" Neat (yield 1.32, weight 14.8). PD 7:30 PM 3-29-95. Bumped plug to 2750 psi for 5 minutes. WOC. Released rig at 10:00 PM 3-29-95. NOTE: Marker joints set 6946-6968' & 8129-8150'. Sandblasted casing set from 6374-7095' and 7467-8195'.

Production Clerk

TITLE

TYPE OR PRINT NAME Rusty Klein

Waiting on completion unit.

DESTRUCT IL SUPERVISOR

ORIGINAL SIGNED BY TIM W. GUM

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

APR 1 2 1995

3-30-95

TELEPHONE NO. 505/748-1471

(This space for State Use)

SIGNATURE

APPROVED BY-