

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

JUL 28 1992

O. C. D.
OFFICE OF

WELL API NO.

Indicate Type of Lease

STATE ☐

FEE ☒

State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

WELL ☒

GAS

WELL ☐

OTHER

2. Name of Operator

Parker & Parsley Development Company

3. Address of Operator

P.O. Box 3178, Midland, Texas 79702

4. Well Location

Unit Letter I : 1980 Feet From The South Line and 785 Feet From The East Line

Section 27 Township 23S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3034 GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Perforate & Frac Bone Springs ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See Attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randy R. Johnson TITLE Sr. Operations Engineer DATE 7/27/92

TYPE OR PRINT NAME Randy R. Johnson TELEPHONE NO. 915-683-4768

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE AUG 10 1992

CONDITIONS OF APPROVAL, IF ANY:

PARDUE FARMS 27 #10, I, Sec. 27, T23S, R28E

Sundry Notice

7/27/92

PBTD: 6788'

7/20/92 Circ hole w/ 2% KCL. POH w/ tbg. RU & perf Bone Springs @ 6739', 6676', 64', 55', 42', 32', 27', 01', 6594', 82', 68', 6441', 35', 6398', 27', 23' (17 holes @ 1 JSPF). RD WL, RIH w/ tbg to 6750'. SDFN.

7/21/92 RU & spot 500 gals 15% HCL from 6750'- 6250'. POH w/ tbg. ND BOP. Install 5-1/2" frac valve. Frac Bone Springs perfs f/ 6323 - 6739' as follows:

STAGE	RATE BPM	FLUID VOL GAL	PROP. CONC. PPG	MASS #	AVG PRESS PSI
1	45	20,000	Pad + 2 dr	Univ. SI-202	3350
2	45	5,500	2	11,000	3100
3	45	6,500	4	26,000	2850
4	45	7,500	6	45,000	2550
5	45	8,500	8	68,000	2350
Total 49,700 gals & 150,000# 20/40 Ottawa sd. ISIP: 2200 psi.					

7/22/92 Flw 5-1/2" csg dwn to pit.

7/23/92 RIH w/ sd bailer, tag'd sd @ 6670' (118' sd). CO sd w/ bailer to PBTD 6788'. SDFN.

7/24/92 TIH w/ 31' MA, 3' perf sub, SN, 10 jts 2-3/8" tbg, TAC & 186 jts 2-3/8" tbg. Set TAC @ 5914'. SN @ 6624', MA @ 6255'. TIH w/ 1-1/2" x 16' pump w/ 6' Stanley sd filter, 12 7/8" rods & 28 3/4" rods. SDFN.

7/25/92 Continue in hole w/ 130 3/4" & 78 7/8" rods. Space out. SDFN.

7/26/92 WO PU.