Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department



DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

VB-407

DEC 3 6 1992

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aziec, NM 87410

P.O. Box 2088 RECEIVED Santa Fe, New Mexico 8/504-2088

DEC 29 1992

O. C. D.

	30-015-27180	
5.	Indicate Type of Lease	

WELL API NO.

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
	Type of Well: OIL AS WELL AS	OTHER		Warthog 2 State
	Name of Operator Santa Fe Energy Operat	ing Partners, L.P.		8. Well No. 2
3.	550 W. Texas, Suite 13	30, Midland, Texas 79	701	9. Pool same or Wildcat East Herradura Bend (Delaware)
4	Well Location	Feet From The North		
777	Section 2	Township 23S Rang	28E	NMPM Eddy County
		10. Elevation (Show whether Df 3073.7'	GR	
11.	Check Ap	propriate Box to Indicate Na	iture of Notice, Re	eport, or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING** TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB XX OTHER: OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/25/92: TD at 6356' @ 8:45 a.m. RU to run logs.

12/26/92: Logging. RU casing crew and begin running 5-1/2" casing.

PERVISOR DISTRICT IF

12/27/92: Ran 140 jts 5-1/2" 15.5# J-55 casing and set at 6356'. FC @ 6306' and DV tool @ 4518'. Cemented 1st stage w/ 325 sx Fremium Plug w/ 8# Silcalite + .6% HAL322 + 2.3# salt. Open DV tool and circ. Had trace of cement to reserve pit. Cemented 2nd stage w/ 1425 sx Cl "C" w/ 6# salt. Tail w/ 100 sx "C" Neat. Circ 117 sx to pit. Plug down at 1:00 p.m. CST. ND BOP's, set slips and cut off. Weld on bell nipple. Jet pits and install head. Released rig at 5:00 p.m. CST. WOCU.

I hereby certify that the information above is true-and complete to the best/of my knowledge and belief. SIGNATURE TYPE OR PRINT NAME Terry McCullough	Dec. 28, 1992 915/ TELEPHONENO. 687-3551
(This space for State Use) ORIGINAL SIGNED BY MIKE WILLIAMS	nsc s a 1002

CONDITIONS OF APPROVAL, IP ANY:

APPROVED BY-