

DISTRICT I

P.O. Box 1930, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-28398
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	REMUDA BASIN 19 FEE
8. Well No.	1
9. Pool Name or Wildcat	NASH DRAW, DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well.	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC. ☒
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>C</u> : <u>510</u> Feet From The <u>NORTH</u> Line and <u>2130</u> Feet From The <u>WEST</u> Line Section <u>19</u> Township <u>23-S</u> Range <u>30-E</u> NMPM <u>EDDY, NM</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3054' GR; 3066' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	PERF & ACIDIZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-28-01: MIRU. WRK STUCK PUMP LOOSE. TOH W/RDS, PUMP & GAS ANCHOR. RUN PARAFFIN KNIFE TO 6850' & CUT PARAFFIN.
 3-01-01: NDWH. NUBOP. TIH W/BIT & CSG SCRAPER ON WS. STOP BIT @ 6635'.
 3-02-01: TAG @ 7310'. TIH W/PRK, & SN ON 2 7/8" TBG. SET PKR @ 6935'. LOAD BACKSIDE W/100 BBLS 2% KCL WTR. TEST TO 500#-OK.
 ACIDIZE BRUSHY CANYON PERFS 7000-72' W/3000 GALS DAD ACID. RU SWAB. FL @ 6000. END FL @ 6000.
 3-05-01: REL PKR. RUN GR/CCL FR 7020-6000 & b 5050-3960. TIH W/PERF GUN & PERF BRUSHY CANYON 6677-6684 & CHERRY CANYON 4672-4698. TIH & PERF BRUSHY CANYON 6120-25 & 6873-76. TIH W/KILL STRING TO 1894'.
 3-06-01: TIH W/CCL & PPI TOOL W/16' SPACING W/BAR TOOLS IN SIDE ON 270 JTS 2 7/8" TBG. SET TOP PKR @ 6868 & BTM PKR @ 6885. ACIDIZE BRUSHY CANYON PERFS 6873-6876 W/300 GALS 15% NEFE HCL. REL PPI TOOL & SET TOP @ 6678 & BTM PKR @ 6690'. ACIDIZE BRUSHY CANYON PERFS 6677-6684 W/750 GALS 15% NEFE HCL. REL TOOL. PULL UP & SET TOP PKR @ 6113 & BTM @ 6130. ACIDIZE BRUSHY CANYON PERFS 6120-25' W/500 GALS 15% NEFE HCL. FISH BAR TOOLS. REL PPI TOOL & TOH TO 4410'.
 3-07-01: TIH W/RBP, PKR & SN ON 2 7/8" WS. SET RBP @ 4740. TEST TO 800#. PULL UP & SET PKR @ 4646'. LOAD & TEST CSG TO 500#-OK. ACIDIZE CHERRY CANYON PERFS 4672-4698 W/2600 GALS 15% NEFE HCL. REL PKR. LATCH & REL RBP. TIH W/KNOTCHED COLLAR ON TBG. TAG @ 7295'.
 3-08-01: TIH W/PURGE VALVE, SN, TBG & TAC. TBG @ 7245'. SN @ 7216'. TAC @ 6918. SET W/18,000#. NDBOP. NUWH.
 3-09-01: RUN PARAFFIN KNIFE TO 6825'. TIH W/GAS ANCHOR, PUMP, SNKR BARS & RDS. LOAD & TEST TO 500#-OK.
 3-12-01: RIG DOWN.
 3-21-01: ON 24 HR OPT. PUMPED 41 BO, 25 BW, & 246 MCF.

BRUSHY CANYON & CHERRY CANYON PERFS 4672-7072.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE MAY 02 2001

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

**ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR**

APPROVED

CONDITIONS OF APPROVAL IF ANY: _____ TITLE _____

DATE MAY 02 2001