

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem tests, including depth interval tested, cushion used, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	GEOLOGIC MARKERS		
				NAME	MEAS. DEPTH	TRUE VERT. DEPTH
Delaware	5890	5920	Oil, gas, & water from production tests	Rustler	114	114
				Top Salt	278	278
				Base Salt	2439	2439
				Delaware	2673	2673
				Bone Spring	6251	6251