Submit 3 Copies to Appropriate District Office	State of New Mex Energy, Minerals and Natural R		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs NM 88240 OIL CONSERVATION DIVISION WELL API NO.			
P.O. Box 1980, Hobbs NM 88240 DISTRICT II	P.O. Box 2088 Santa Fe, New Mexico 805 94 2 0 8 8 1997		30-015-29477
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	MAY41 28 1997	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	OF:		6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PRODIFFERENT RESELLATION OF CORMIC)	ICES AND REPORTS ON WELL OPOSALS TO DRILL OR TO DEEPEN O RVOIR. USE "APPLICATION FOR PERI -101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Weems
1. Type of Well: OIL GAS WELL X WELL	OTHER		
2. Name of Operator Santa Fe Energy Resource	es. Inc.		8. Well No.
3. Address of Operator 550 W. Texas, Suite 133			9. Pool name or Wildcat Undes. Esperanza Delaware
4. Well Location Unit Letter F : 203	7 Feet From The North	Line and190)1 Feet From The West Line
Section 27 Township 22S Range 27E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3116' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
		SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. X PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB
OTHER:		OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			
5/3/97: Spud 17-1/2" hole at 8:00 p.m. Drlg.			
5/4/97: Drilling.			
5/5/97: TD 17-1/2" hole at 450'. RU casing crew & ran 11 jts 13-3/8" 48.0# H-40 ST&C casing and set at 450'. Cement 1st stage w/ 300 sx Cl "C" containing 6% gel, 2% CaCl2, & 1/4 pps celloflake. Cement 2nd stage w/ 200 sx Cl "C" + 2% CaCl2. Cement did not circulate. WOC.			
5/6/97: WOC. Run temp survey. TOC @ 90'. RIH w/ 1" and cement w/ 105 sx Cl "C". Cement circulated 25 sx surface. WOC. Cut drlg line. Cut off 13-3/8" casing and weld on head, test weld. NU BOP. PU BHA & TIH. Test csg to 600 psi, ok. Resume drilling operations.			
Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE OSCIPLE DATE 05/09/97			

TYPE OR PRINT NAME Terry McCullough TELEPHONE NO.915/687-3551 (This space for State Use) ORIGINAL SIGNED BY TIM W. GUM DATE MAY 1 4 1997 DISTRICT II SUPERVISOR TITLE