


- Safety Factor - High Voltage

Location was turned because
of electric lines too close to derrick
& Telephone pole in line of hole.

(Before - Pits to the north & Derrick to
the east)



- ⚓ Wind Direction Indicators
(wind sock or streamers)
- △ H₂S Monitors
(alarms at bell nipple and shale shaker)
- Briefing Areas
- Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"
RIG LAYOUT PLAT

POGO PRODUCING COMPANY
LOST TANK "4" FEDERAL #5
SECTION 4 UNIT F
T22S-R31E EDDY CO