Form 3160 CEIVED BY UNLED STATES (November 19-331) DEPAR MENT OF THE INTERIO	SUBMIT IN TRIPL. TE* (Other instructions on reverse side)	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.
MAY 10 1985 BUREAU OF LAND MANAGEMENT		NM 38459
SUNDRY NO ICES AND REPORTS OF ONE CONTROL OF THE CO	N WELLS k to a different reservoir. socials.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. Off. 631 C18 C7		7. UNIT AGREEMENT NAME
WELL A WELL OTHER RE-Entry	NU OTT COMO COMO	
Yates Petroleum Corporation	NM OIL CONS. COMMI	T
3. ADDRESS OF OPERATOR	Artesia, NN 88210	Welch "ABV" Federal
207 South 4th St., Artesia, NM 88210	MI CODIA, NA CORIO	1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*		10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface		Wildcat - Boy Soring
660 FNL & 760 FWL, Sec. 21-T26S-R27E		11. SBC., T., B., M., OR BLK. AND
, =====================================		SURVEY OR AREA
		Unit D, Sec. 21-T26S-R27E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, R	T, GR, etc.)	12. COUNTY OR PARISH 13. STATE
3235' GR		Eddy NM
16. Check Appropriate Box To Indicate Nati	ture of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF PULL OR ALTER CASING		
FRACTURE TREAT MULTIPLE COMPLETE	WATER SHUT-OFF	REPAIRING WELL
SHOOT OR ACIDIZE ABANDON*	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ABANDONMENT®
REPAIR WELL CHANGE PLANS	(Other)	
(Other) Clean out well & complete X	(Note: Report results	of multiple completion on Well etion Report and Log form.)
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent of proposed work. If well is directionally drilled, give subsurface location nent to this work.) 	letnils and give pertinent dates	including agrimated data of starting and
Propose to set cement plug at 700'±. Squeez plug at 5300'±. Run spring mill to 7" casing casing stub, run 7" casing w/slip joint show Clean out retainer at 5870'. Pressure test Drill out squeeze and clean out to 5914', to	ng stub. Run skirte e and squeeze 7" cas perfs at 5650-5840'	d mill and dress 7" ing patch Squeeze to 2500#.
18. I hereby certify that the foregoing is true and correct		1 1985
	action Supervisor	DATE 4-30-85
(Tills space-for Federal or State office use)		DATES 5-9-85
APPROVED BY		DATE

*See Instructions on Reverse Side