

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 38459

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Welch ABV Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat Bone Springs

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Unit D, Sec. 21-T26S-R27E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

105 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

660' FNL & 760' FWL, (NW/NW)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3235' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Continue Suspended Production X

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Due to economic conditions this well has been suspended from production. The suspension expires May 31, 1989. Yates Petroleum Corporation would like to continue the well in suspension and ask for your approval.

1. The lease in in its extended term.
2. All wells on the lease are shut-in or P&A.
3. The well is capable of production as a marginal well.
4. At last date of production the well was capable of producing in paying quantities, with the exception of rod part, uneconomical to repair at this time. Failure to suspend could lead to premature abandonment.
5. The well produced 196 BOPM during the last five months of 1985 and the first four months of 1986. The last month of production was August, 1986 at which time the well produced 4 BOPM.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Supervisor

DATE 5-8-89

(This space for Federal or State office use)

APPROVED BY

FOR TITLE

DATE 5-19-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side