PORT 9-831 a (Feb. 1961)  UNITED  DEPARTMENT OF  GEOLOGIC  AND SERVICE ENGINEER  30-015-0	Budget Bureau No. 42-R358.4. Approval expires 12-31-60.  I TRIPLICATE)  Lease No. NM. 31-375-A  Unit TM*  Unit TM*  D REPORTS ON WELLS
NOTICE OF INTENTION TO DRILL  NOTICE OF INTENTION TO CHANGE PLANS  NOTICE OF INTENTION TO TEST WATER SHUT-OFF  NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL  NOTICE OF INTENTION TO SHOOT OR ACIDIZE  NOTICE OF INTENTION TO PULL OR ALTER CASING  NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY
Well No is located	
Mudded hole. Set following cement pl:  15 sxs - 3448' - 3498' 35 sxs - 900' - 1050' 35 sxs - 540' - 600' 15 sxs - Top of surface	ugs: (사원) (사원 : 1961
Recovered 2750 of 42 casing.  Placed 4" marker. Pits have not presently been leveled. First opportunity when equipment is available, location will be leveled.  I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.  Company Curtis Hankamer	

Address 1422 Bank of the Southwest Bldg.

-----Houston-2, Texas-----

Phil C. Hankamer
Title Engineer