

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4856
7. Unit Agreement Name
8. Farm or Lease Name Eddy "FD" State
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat (Dev.)
12. County Eddy

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Gulf Oil Corporation
3. Address of Operator Box 670, Hobbs, New Mexico	4. Location of Well UNIT LETTER F , 1980 FEET FROM THE north LINE AND 1980 FEET FROM THE west LINE, SECTION 28 TOWNSHIP 25S RANGE 28E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 2977' GL	16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Received verbal permission to plug and abandon, Mr. Armstrong to Mr. Bruce, 10:00 a.m., July 15, 1965. Plugged and abandoned as follows:
7928' FB. Conditioned mud. Pulled out of hole. Cut 9-5/8" casing with jet cutter (clean cut) at 8995' (12' below cellar). Displaced brine in 9-5/8 - 13-3/8" annulus with 9.8# mud. Laid down 212 jts & 2 out jts 9-5/8" csg. Ran drill pipe open ended, spotted cement plugs 7700-7600' with 30 sacks Incer w/4% Gel; 7045-6945' with 55 sacks Incer w/4% Gel; 6200-6100' w/75% Incer w/4% Gel & 2% Ca Cl2; 2450-2330' w/75% Incer w/4% Gel & 2% Ca Cl2. Laid down drill pipe. Tagged cement plug at 2330'. Spotted cement plug 60' to surface w/30 sacks Incer w/4% Gel and 2% Ca Cl2. Set dry hole marker. Plugged and abandoned July 18, 1965.

RECEIVED

JUL 21 1965

O. C. C.
ARTERIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE **Area Production Manager** DATE **July 19, 1965**

APPROVED BY **W. A. Gressett** TITLE _____ DATE **JAN 5 1966**

CONDITIONS OF APPROVAL, IF ANY: