

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
State - K-4562	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name Cotton Draw Unit
2. Name of Operator TEXACO Inc. ✓	8. Farm or Lease Name Cotton Draw Unit
3. Address of Operator P. O. Box 728 - Hobbs, New Mexico	9. Well No. 65
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 25-S RANGE 31-E NMPM.	10. Field and Pool, or Wildcat Morrow & Wolfcamp
15. Elevation (Show whether DF, RT, GR, etc.) 3475' (D. F.)	12. County Eddy

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Plugs &amp; Perforate</u> <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1705.

The following work has been completed on subject well:

1. Cemented a 60 Sx. plug from 18,800' to 18,630', (Ellenburger)
2. Cemented a 60 Sx. plug from 17,220' to 17,070', (Fusselman)
3. Cement 450 Sx. from 16,780' to 16,070', top of cement at 16,070'. Set Cast Iron Bridge Plug at 15,050'. Set Model D Packer at 14,700'.
4. Perforate the Morrow Pool with one jet shot per foot from 14,787' to 14,795', 14,813' to 14,835', 14,846' to 14,853', and 14,863' to 14,867'.
5. Perforate the Wolfcamp Pool with two jet shots at 12,785', 12,803', 12,814', 12,824', 12,828', 12,840', 12,846', & 12,851'.
6. Test, and install production equipment.

RECEIVED

JUN 29 1967

O. C. C.  
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. G. Blevins, Jr.</u>	TITLE <u>Assistant District Supt.</u>	DATE <u>June 27, 1967</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u>OIL AND GAS INC.</u>	DATE <u>JUL 12 1967</u>
CONDITIONS OF APPROVAL, IF ANY:		