

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NM OIL & GAS
Artesia, NM 88210

SECTION

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0525452-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Cities 3 Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Washington Ranch - Delaware

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 3, T26S, R24E

12. COUNTY OR PARISH

Eddy

13. STATE
New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Alpha Twenty-One Production Company

3. ADDRESS OF OPERATOR

2100 First National Bank Building, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL and 660' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3750 Ground Level

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)


Formally Plug Back this well?

We propose to Plug and Abandon this well using the following procedure:

Set CIBP at 1400' and dump 35' of cement on top.
Place 15 sacks cement plug at the surface.
Erect monument at wellsite.

(Temperature survey shows top of cement on production string at 640')

**Perforate 75 ft. below surface casing shoe and squeeze with
100 sacks of cement.



OIL & GAS
U.S. GEOLOGICAL SURVEY
LOS ALAMOS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Tommy Phillips

TITLE Executive Vice President

DATE September 18, 1981

(This space for Federal or State office use)

APPROVED

APPROVED BY (Orig. Sgd.) PETER W. CHISTER

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

SEP 24 1981

FOR

JAMES A. GILL
DISTRICT SUPERVISOR

See Instructions on Reverse Side