Form 9-33t (May 1963)

## ilten, staj THE INTERIOR (Other Instructions on re-

SUBMIT IN TRIPLICATE.

Form approved. Budget Bureau No. 42-R1424 5. LEASE DESIGNATION AND SERIAL NO.

NN	1_	າ	6	6	7	7

GEOLOGICAL SURVEY	NM-26677
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
CAS WELL OTHER	7. UNIT AGREEMENT NAME
ME OF OPERATOR	

S. FARM OR LEASE NAME FEB 0.9 1983 Gulf Oil Corporation East Chosa Draw Fed 3. ADDRESS OF OPERATOR 9. WELL NO. P. O. Box 670, Hobbs, NM 10. FIELD AND POOL, OR WILDCAT

LOCATION OF WELL (Report location clearly and in accordance with any State requirements. At surface 1980' FNL & 1980' FEL

Wildcat 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3501' GL 16.

Sec 22-T25S-R25E 12. COUNTY OR PARISH | 13. STATE

Eddy NM

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF	INTENTION TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING Re-ABANDONMENT X
REPAIR WELL	CHANGE PLANS	(Other)
(Other)		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.).

Cut off dry hole marker. Tag plug at 636', drill cement to 700'. Tag plug at 1643', drill cement to 1740'. Tag plug at 8450', drill cement to 8550'. Circulate hole. Set CIBP at 8540'. Spot 25 sack plug 8440' - 8540'. Spot 25 sack plug 1770' - 1870'. Spot 25 sack plug 750' - 850'. Spot 10 sack surface plug. Weld on dry hole marker. Clean and clear location. Complete after re-plugging.

Above procedure approved verbally by George Stewart 6-3-82.

DISTRICT SUPERVISOR

OIL & GAS J.S. GEOLOGICAL SURVEY

I hereby certify that the foregoing is true and correct SIGNED Pite	TITLE	Area Engineer	DATE	7-21-82
This space for Federal carper CVED (CHESTER OF APPROVAL, IF ANY:	TITLE		DATE	
FEB 8 1983 FOR JAMES A. GILLHAAI *Se	Instruction	ns on Ravarsa Sida		