

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
AUG 20 1993
DIST. 8 BLM
Conservation and Management

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

SEP 17 1993

C.I.D.

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Fortson Oil Company

3. Address and Telephone No.
301 Commerce, Ste 3301, Fort Worth, TX 76102 (800) 878-3300

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
660' FNL & 660' FEL of Sec. 25, T-24-S, R-30-E

5. Lease Designation and Serial No.
LC-061705-B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Poker Lake Unit No. 78

9. API Well No.
30-015-27536

10. Field and Pool, or Exploratory Area
Poker Lake Delaware

11. County or Parish, State
Eddy

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

ORIGINAL
COMPLETION

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Completion Operations will begin Friday 8/27/93 with your approval; no additional pits will be constructed,

1. Move in and rig up completion equipment.
2. Perforate 7,944' to 7964' KB.
3. Acidize and test.
4. Isolate zone.
5. Perforate 7,856' to 7,870' KB.
6. Acidize and test.
7. Combine zones.
8. Fracture treat.
9. Flow/swab to clean up, run potential test and initiate production.

14. I hereby certify that the foregoing is true and correct.

Signed James E. Brown Title Agent for Fortson Oil Company Date 8/26/93

(This space for Federal or State office use)

Approved by [Signature] Title AGENT Date 9/14/93
Conditions of approval, if any: