IN IN U. C. C. COBY

' 'ITED STATES DEPART!...NT OF THE INTERIOR Of ther instruction of the interior of the interior of the instruction of the i

ACATE*

Form approved. Budget Dureau No. 42 R1124.

5. LEASE DESIGNATION AND SERIAL NO.

064894 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

The state of the s

GEOLOGICAL SURVEY

SUNDRY NO (Do not use this form for pro- Use "APPI"	ONCES AND REPORTS ON Opensals to drill or to deepen or plug back ACATION FOR PERMIT—" for such proposed.	WELLS to a different reservoir.		TILL OR TRIBE NAME
OIL GAS	RECEIVE	D RECEIV	TO IT AGREEMEN	T NAME
WELL X WELL OTHER			Poker Lake	•
2. NAME OF OPERATOR	MAY 8 1970	MAY 7 - 19	70 8. FARM OR LEASE	NAME
PERRY R. BASS 3. ADDRESS OF OPERATOR	MAY 8 1970	U. S. GEOLOGICA	Continantal	Federal
	marrie goge/ [] H =			
4. LOCATION OF WELL (Report location	Texas 79756 日. C. C. n clearly and in ARTHEME, WHIPPE State north line and 660' from	requirements.*	10. FIELD AND POO	L. OR WILDCAT
At surface 6601 from the	north line and 6601 from	the west line	- A	第 - -
of Section 20, Townshi New Mexico	p 25 South, Range 30 East	, Eddy County,	11. SEC., T., E., M., SURVEY OR A	n Delaware Ext.
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT,	TP ata \	Sec. 20, T- 12. COUNTY OR PAI	25-S, R-30-E
		•		
16. CL -1	3204 Orig. KD		Eddy	INew Mexico
Check A	Appropriate Box To Indicate Natur	e of Notice, Report, or	Other Data	
NOTICE OF INC	TENTION TO:	SUBSE	QUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRI	NG WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT		G CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDON	MENT*
REPAIR WELL	CHANGE PLANS	(Other)	# * , ja	
(Other)	OPERATIONS (Clearly state all pertinent det ctionally drilled, give subsurface locations	(Note: Report resul Completion or Recom	ts of multiple completing the second Log	lon on Well g form.)
perforations: 3671-3673 perfs with fresh water	ata: 3761 TD. 3686 PBTD.; 3664-3666. We propose and swab via casing with OD casing with 10,000 ga	to pull pumping ϵ	equipment, the	n wash the
	ADDITIVES	CONCENTRATION		***********
FLUID	(PER 1000 GALLONS)	LBS/GAL.	OT OT	AMOUNT,
2,500 gal. 2% KCl Water	50 lbs. Adomite Aqua		SIZE	LBS.
2,500 gal. My-T-Frac	50 los. WAC-9			
1,500 gal. My-T-Frac	50 lbs. WAC-9	1.0	20-40	1,500
1,500 gal. My-T-Frac	50 lbs. WAC-9	2.0	10-20	3,000
1,500 gal. My-T-Frac	25 lbs. WAC-9	3.0	10-20	4,500
1,500 gal. My-T-Frac	25 lbs. WAC-9	3.0	8-12	4,500
l,500 gal. My-T-Frac	25 lbs. WAC-9	4.0	8-12	6,000
in an effort to place a	treatment, it will be de large concentration of c	liberately "sande parse sand near t	ed out" with 8 the well bore.	-12 mesh sand
should be made on or abo	out May 7, 1970.			
		•		S TATE
10 7 1			3 d () } k ()	
18. I hereby certify that the foregoing		ent Division Mana	ger DATE May	4.F1970
(70)			DAID SIGN	

*See Instructions on Reverse Side