# MINIMUM BLOWOUT PREVENTER REQUIREMENTS

#### 2.,000 psi Working Pressure

#### 2 MWP

# MACK ENERGY CORPORATION EXHIBIT #1-A

CONFIGURATION

### STACK REQUIREMENTS

	I .		Min.	Min.
Nρ.	Item		I.D.	Nominal
1	Flowline			
2	Fill up line			2"
3	Drilling nipple			
4	Annular preventer			
5	Two single or one dual hydraulically operated rams			
6 <b>a</b>	Drilling spool with 2" min. kill line and 3" min choke line outlets			2"choks
6b	2" min. kill line and 3" min. choke line outlets in ram. (Alternate to 6a above.)			
7	Valve	Gate [] Plug []	3-1/8"	
8	Gate valve—power operated		3-1/8"	
9	Line to choke manifold			3"
10	Valves	Gale [] Plug []	2-1/16"	
11	Check valve		2-1/16*	
12	Casing head			
13	Valve	Gate □ Plug □	1-13/16"	
14	Pressure gauge with needle valve			
15	Kill line to rig mud pump manifold			2*

ANNULAR PREVENTER  BLIND RAMS  BLIND RAMS  ORILLING SPOOL  TO BE CASING HEAD  GEORGE STATES OF THE CASING HE		
ANNULAR PREVENTER  BLIND RAMS  PIPE RAMS  ORILLING SPOOL  TO 13  9  CASING HEAD		
PREVENTER  BLIND RAMS  PIPE RAMS  ORILLING SPOOL  TO IS  CASING HEAD  PREVENTER  BLIND RAMS  ORILLING  ORI		
PIPE RAMS  PIPE RAMS  ORILLING  ORILLING  TORILLING  HEAD  ORILLING  ORILLIN		·
PIPE RAMS  PIPE RAMS  ORILLING  ORILLING  TORILLING  HEAD  ORILLING  ORILLIN		
PIPE RAMS  ORILLING  ORILLING  TORILLING  ORILLING  ORIL		BLIND RAMS
ORILLING SPOOL TO BE AS HEAD HEAD HEAD		
CASING HEAD TO		(a)
SPOOL TO THE SPOOL		T '/\
CASING HEAD HEAD	1	DRILLING
HEAD		
GASING (2)		CABING HEAD PO
		(6) CASING (2)

OPTIONAL		
16 Flanged valve	1-13/16"	
10 Hangea totte	·	

## CONTRACTOR'S OPTION TO FURNISH:

- 1.All equipment and connections above bradenhead or casinghead. Working pressure of preventers to be 2,000 psl, minimum.
- Automatic accumulator (80 gallon, minimum) capable of closing BOP in 30 seconds or less and, holding them closed against full rated working pressure.
- 3.80P controls, to be located near drillers position.
- 4. Kelly equipped with Kelly cock.
- Inside blowout prevventer or its equivalent on derrick floor at all times with proper threads to fit pipe being used.
- Kelly saver-sub equipped with rubber casing protector at all times.
- 7. Plug type blowout preventer tester.
- Extra set pipe rams to fit drill pipe in use on location at all times.
- 9. Type RX ring gaskets in place of Type R.

#### MEC TO FURNISH:

- 1.Bradenhead or casinghead and side
- 2. Wear bushing, if required.

#### GENERAL NOTES:

- Deviations from this drawing may be made only with the express permission of MEC's Drilling Manager.
- 2.All connections, valves, fittings, piping, etc., subject to well or pump pressure must be flanged (suitable clamp connections acceptable) and have minimum working pressure equal to rated working pressure of preventers up through chore. Valves must be full opening and suitable for high pressure mud service.
- Controls to be of standard design and each marked, showing opening and closing position.
- 4. Chokes will be positioned so as not to hamper or delay changing of choke beans. Replaceable parts for adjustable choke, other bean sizes, retainers, and choke wrenches to be conveniently located for immediate use.
- 5.All valves to be equipped with handwheels or handles ready for immediate
- 6. Choke lines must be suitably anchored.

- 7.Handwheels and extensions to be connected and ready for use.
- Valves adjacent to drilling spool to be kept open. Use outside valves except for emergency.
- 9.All seamless steel control piping (Z000 psi working pressure) to have flexible joints to avoid stress. Hoses will be permitted.
- Casinghead connections shall not be used except in case of emergency.
- 11.Do not use kill line for routine fill-up operations.