	**	*		
په س		/		
Submit 3 Copies To Appropriate District	State of N	lew Mexico		F C 102
Office		,		Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, witherais at	nd Natural Resource	WELL API NO.	Revised March 25, 1999
District II				045 20205
811 South First, Artesia, NM 88210	OIL CONSERVA	ATION DIVISION	\ <u> </u>	-045-29225
District III	1220 South 5	St. Francis Dr.	5. Indicate Type	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe.	NM 87505	STATE	☐ FEE 🗶
1220 S. St. Francis Dr., Santa Fe, NM		- 1112 0 7 5 0 0	6. State Oil &	Gas Lease No.
87505				
SUNDRY NOTICES AND REPORTS ON WELLS 7. 3 4 5 6 5. 7. Lease Name or Unit Agreement Name:				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PEUG BASK TO A ODDIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				
PROPOSALS.)	CATION FOR FERMIT (FORM		4	
1. Type of Well:		FEB 2003	Woo	ds Gas Com B
Oil Well Gas Well	Other		ા. તી	
2. Name of Operator		163 C.	8. Well No.	
BP America Production Company	Attn:	Cherry Hlava	, Won two.	1
3. Address of Operator	7,1,1	Variation	9. Pool name or	Wildcat
_	77253	Q man s	11.21	rured Cliffs, West
4. Well Location		al College	Ruiz Fici	area ciijis, wesi
Wen Because				
Unit Letter M	1520 feet from the	South line and 1	150 feet from the	Vest line
	root from the	mic and	150 leet nom the	<u>vesi</u> nne
Section 7	Township 29N R	lange 12W	NMPM San Jud	an County
	10. Elevation (Show wh			in County
	10. Elevation (Bnow with	5476'	JA, etc.)	
11 Check /	Anneanriata Day to Indi	•	tion Domant on Other	Dodge
NOTICE OF IN	Appropriate Box to Indi			
	TENTION TO:		SUBSEQUENT RE	
PERFORM REMEDIAL WORK	J PLUG AND ABANDON	☐ REMEDIAL	WORK	ALTERING CASING \Box
TEMPORARILY ABANDON	CHANGE PLANS	COMMENC	E DRILLING OPNS.	DI LIC AND
TEMPORARILY ABAINDON	CHANGE PLANS	L COMMENC	E DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE	☐ CASING TE	ST AND	ABANDONWENT
	COMPLETION	CEMENT JO		
OTHER:		OTHER: T	&A	
12. Describe proposed or comple	ted operations. (Clearly sta-	te all pertinent details,	, and give pertinent dates	, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompilation.				
On 7/11/02 BP America requested permission to T&A above mentioned well. Approval was granted 7/15/02.				
Please see the attached to show well was T&A'd 1/7/03.				
			Fee 3 13	
			10	1.7
	. , , , , , , , ,			
	- LALTO		*40370'	ST
	ad chartok		The state of the s	
Market and the second s				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE / hate	lane of more	DI D		
SIGNATURE Chury for	rava III	TLE <u>Regulatory A</u>	<u>nalyst</u> DATE _	01/14/2003
Type or print name Cherry H	lava		Telephone No.	281-366-4081
(This space for State use) /				
APPROVED BY Charles T. TITLE S GAS INSTRUCTOR, SAST. AND				
APPPROVED BY Charle ?		TITLE	CIST, SAY, CO	DATE -
APPPROVED BY Chart 1 TITLE Conditions of approval, if any: TITLE TITLE TITLE				
11 , , -				-000

*

TA OPERATION SERVICE REPORT

WELL NAME: WOODS GAS COM B #1

TOTAL PLUGS: NA

DATE STARTED: 1-7-03

TOTAL SACKS: NA

DATE COMPLETED: 1-8-03

WITNESS: NONE

MOL & RU. CHECK PRESSURE. 60 LBS ON CASING. O LBS ON TBNG. BLOW DOWN CASING. ND WELL HEAD. NU BOP. STRAP OUT OF HOLE (1476'). SCRAPER RUN. RU WIRELINE & SET 3 1/2" CIBP @J 1450'. TIH & TAG CIBP. LD 1 JNT TBNG. LOAD HOLE AND PRESSURE TEST W/FMC ON CHART 550 PSI FOR 30 MINUTES. CIRCULATE HOLE W/PACKER FLUID. LD 6 JNTS TBNG @ 1276'. ND BOP. NU WELL HEAD. RD & MOVE OFF LOCATION.



RANDY BLACKMON



