Form 3160-5 UNITED STATES (November 1994)  DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals			FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996  5. Lease Serial No. NMO70322  6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRI	PLICATE – Other instri	uctions on reverse side 4 🐧	7. If Unit or CA/Agreement, Name and/or N 8: 04	
1. Type of Well Gas Well Other 070 FARMING (			Carson Unit	
2. Name of Operator			Carson Unit 15 #33	
Elm Ridge Resources, Inc.			9. API Well No.	
3a. Address		3b. Phone No. (include area code)	30-045-05374	
PO Box 189 Farmington, NM 87499		505-632-3476	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Bisti Lower Gallup	
1980' FNL & 1980' FEL Sec. 15-T25N-R12W  12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OT			San Juan, NM	
TYPE OF SUBMISSION	TYPE OF ACTION	TORE OF NOTICE, REPORT, OR OF	ILK DATA	
TIPE OF SUBMISSION	TIPE OF ACTION			
Notice of Intent  Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	Fracture Treat Reclamation	racture Treat Reclamation Well Integrity	
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Temporari Plug Back Water Dis	rily Abandon sposal	
If the proposal is to deepen direction Attach the Bond under which the war- Following completion of the involved	mally or recomplete horizontally, give ork will be performed or provide the operations. If the operation results in Abandonment Notices shall be filed	ails, including estimated starting date of any pro subsurface locations and measured and true vertic Bond No. on file with BLM/BIA. Required sul in a multiple completion or recompletion in a new only after all requirements, including reclamation,	cal depths of all pertinent markers and zones.  because treports shall be filed within 30 days  v interval, a Form 3160-4 shall be filed once	
Pump 135 sks cmt, sting Shoot 2 holes @ 1060', se	out place 5 sks on top of et retainer @ <mark>960</mark> ' pump 2	retainer. Plug 2. 1 <del>5 sk balanced</del> 26 sks cmt, sting out leave 6 sks		

Shoot 2 holes @ 1060', set retainer @960' pump 28 sks cmt, sting out leave 5'sks on top. Plug 4. Shoot 2 holes @300'. Set retainer @250' Pump 100 sks cmt circulate to surface. Plug 5. Pump 25 sks cmt. from 250' to surface inside 4-1/2'. Cut off casing place dry hole marker with information welded on. Reclaim surface.

Note: 8-5/8"

Surface @100', 4-1/2" production Casing @4863'. 3-1/2" scab liner 1688'-3740'.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Terry Lindeman District Superintendent Date Signature May 1, 2004 THIS SPACE FOR FEDERAL OR STATE USE Original Signed: Stephen Mason Approved by Title Date MAY 0 6 2004 Conditions of approval, if any, are attached Approval of this notice does not warrant or Office certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)