Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

$\overline{}$
.,
~1
,,

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

5. Lease Serial No.

NMSF	-079383		

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRI	PLICATE - Other instruc	ctions on rev	erse side.		7. If Unit or CA/Agree	ment, Name and/or No.	
1. Type of Well	·		8. Well Name and No.				
Oil Well 🛛 Gas Well 🗖 Oth	ier			}	SJ 30 6 95R		
2. Name of Operator BURLINGTON RESOURCES	TAMMY WIM E-Mail: twimsa			9. API Well No. 30-039-20520-00-S2			
3a. Address PO BOX 4289 FARMINGTON, NM 87499	3b. Phone No Ph: 505.59 Fx: 505.599)	10. Field and Pool, or Exploratory LA JARA PICTURED CLIFFS			
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Descriptio	n)			11. County or Parish,	and State	
Sec 26 T30N R7W SWSW 80			RIO ARRIBA CO	DUNTY, NM			
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF I	NOTICE, RI	EPORT, OR OTHE	RDATA	
TYPE OF SUBMISSION		 	TYPE OF ACTION				
Nation of Intent	☐ Acidize	Deep	pen	Product	ion (Start/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	_	ture Treat	Reclam	ation	☐ Well Integrity	
Subsequent Report	Casing Repair	☐ New	Construction	☐ Recomp	olete	Other	
Final Abandonment Notice	Change Plans		and Abandon	☐ Tempor	arily Abandon		
3	Convert to Injection	. —	Plug Back Water Disposal				
determined that the site is ready for f 3-25-04 MIRU. Blow well & C 3-26-04 Pump hot wtr down of @ 600'. Release pkr @ 3025'. 3-29-04 TIH w/fishing tools to SDON. 3-30-04 Fishing. SDON. 3-31-04 Fishing. TOOH w/fish 4-1-04 TIH w/fishing tools. Fi hole clean. TIH w/7" gauge rin TIH w/7" cmt retainer, set @ 3 pump 72 sx Class "B" neat cm	O. (Herman Lujan, BLM sg. TOOH w/rods & pum SD for weekend. top of fish @ 750'. Fishin, fishing tools & pkr. TIH shing. TOOH w/fish & fisg, tag top of fish @ 3707686'. Load tbg w/12 bbly it inside csg @ 3313-368	mp. ND WH. No mg. (Virgil Luc w/7" gauge ri hing tools. Lo ''. TOOH. PT	J BOP. TOOH vero, BLM on loc ng. Top of fish (and csg w/14 bbl of csg to 600 ps 1000 psi. follod	ation). ② 2958'. SD wtr. Circ i/20 min, Ok	ON.	no la retalnos un	
14. I hereby certify that the foregoing is	true and correct. Electronic Submission a For BURLINGTON RI	#30745 verified ESOURCES O	by the BLM Wel	I Information to the Farmin	System aton		
Committed to AFMSS for processing by ST Name (Printed/Typed) NANCY OLTMANNS			EVE MASON on 05/18/2004 (02SXM0507S) Title SENIOR STAFF SPECIALIST				
Signature (Electronic Submission) Dat			Date 05/14/2	004			
	THIS SPACE FO	OR FEDERA			SE		
Approved By ACCEPT	STEPHEN TitlePETROLE		ER	Date 05/18/2			
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu	Office Farming	ıton					

Additional data for EC transaction #30745 that would not fit on the form

32. Additional remarks, continued

top. WOC. (Virgil Lucero, BLM on location). SDON. 4-2-04 TiH, tag TOC @ 3679'. Load csg w/14 bbl wtr. PT csg to 1000 psi, OK. Plug #2: pump 59 sx 4-2-04 TiH, tag TOC @ 3679'. Load csg w/14 bbl wtr. PT csg to 1000 psi, OK. Plug #2: pump 59 sx Class "B" neat cmt inside csg @ 3373-3679' to isolate Pictured Cliffs & cover Fruitland top. WOC. TOOH. TIH, perf 3 sqz holes @ 2984'. TOOH. Attempt to establish injection. TIH to 3055'. Plug #3: TOOH. TIH, perf 3 sqz holes @ 2537-3035' to cover Kirtland & Ojo Alamo tops. TOOH. SD for pump 96 sx Class "B" neat cmt @ 2537-3035' to cover Kirtland & Ojo Alamo tops. weekend.
4-5-04 Tag TOC @ 2569'. Circ hole clean. PT csg to 500 psi/30 min, OK. TOOH. TIH, perf 3 sqz holes @ 1552'. TOOH. Attempt to establish injection. (Verbal approval to change plans from Virgil Lucero, BLM). TIH to 1584'. Plug #4: pump 60 sx Class "B" neat cmt w/2% calcium chloride inside csg [1273-1584' to cover Nacimiento top. TOOH. WOC. TIH, tag TOC @ 1381'. TOOH. TIH, perf 3 sqz holes @ 273'. Establish circ down csg & out bradenhead w/15 bbl wtr. Plug #5: pump 151 sx Class "B" neat cmt down 7" csg & out bradenhead. Circ 1 bbl cmt to surface. WOC. ND BOP. Cut off WH. Cmt @ surface in 7" csg & annulus. Install dry hole marker w/25 sx Class "B" neat cmt. SDON. 4-6-04 RD. Rig released.

Well plugged and abandoned 4-5-04.