



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

October 1, 2004

Gary Brink
Energen Resources
2198 Blmfld Hwy
Farmington NM 87401

RE: Jicarilla 98 #12A, N 18-26N-03W API 30-039-27312

Dear Mr. Brink:

The 2004 Packer Leakage Test on the referenced well does not provide the required crossover information for the zones. In order to comply with Rule #112A, you are hereby directed to retest the well to show separation of the zones prior to November 1, 2004. Notify the Aztec OCD in time to witness the retest.

Reference CTP0423752123 on all future correspondence including the test report.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: CTP
Well File