UNITED STATES		
DEPARTMENT OF THE INTERIOR		
BUREAU OF LAND MANAGEMENT		
Sundry Notices and Reports on Wells		<del></del>
. Type of Well GAS RECEIVE	0.	Lease Number NMSF-078384 If Indian, All. or Tribe Name
070 FARMINGT	TON HH.	Unit Agreement Name
Name of Operator  BURLINGTON  RESCURCES OIL & GAS COMPANY LP		·
	8.	
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	Newsom B #3 API Well No. 30-045-05913
. Location of Well, Footage, Sec., T, R, M 1450'FSL, 990'FWL, Sec.8, T-26-N, R-8-W, NMPM	10.	Field and Pool Basin Fruitland Coal
	11.	Ballard Pictured Cli County and State San Juan Co, NM
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPOR	RT. OTHER	DATA
	nge of Pl Construc	
		Fracturing
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv	-Routine er Shut o	Fracturing
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -	-Routine er Shut o	Fracturing ff
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  3. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  3. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  3. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  3. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  3. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  3. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  B. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  B. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  B. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  3. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  B. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Final Abandonment Altering Casing Conv Other -  B. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non-Casing Repair Wate Altering Casing Conv Other -  3. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc procedure and wellbore diagram.	-Routine er Shut o version t	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Altering Casing Conv Other -  3. Describe Proposed or Completed Operations It is intended to plug and abandon the subject well acc procedure and wellbore diagram.	Routine or Shut of version to the cording to the cordinal co	Fracturing ff o Injection
Subsequent Report Plugging Back Non- Casing Repair Wate Altering Casing Conv Other -  3. Describe Proposed or Completed Operations  It is intended to plug and abandon the subject well acc procedure and wellbore diagram.  4. I hereby certify that the foregoing is true and correct igned Many Olimanno Title Senior Staff Special	Routine or Shut of version to the cording to the cordinal co	Fracturing  ff o Injection  o the attached
Subsequent Report Plugging Back Non- Casing Repair Wate Altering Casing Conv Other -  3. Describe Proposed or Completed Operations It is intended to plug and abandon the subject well acc procedure and wellbore diagram.	Routine or Shut of version to the cording to the cordinal co	Fracturing  ff o Injection  o the attached

submitted in lieu of Form 3160-5

# Newsom B #3 – PC / FT Well PLUG AND ABANDONMENT PROCEDURE

1450' FSL & 990' FWL SW, Section 8, T026N, R008W Latitude: N 36^ 29.916", Longitude: W 107^42.636 AIN: 3207001/ 327002 10/6/04

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

All cement will be ASTM Type III, mixed at 14.8 ppg with a 1.32 cf/sx yield.

- 1. Install and test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Burlington safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line and blow down well; kill with water as necessary.
- 2. Pressure test tubing to 1000#, then pull and LD rods. ND wellhead and NU BOP, test BOP. TOH with 66 joints 2-3/8" tubing, 2079'. Round trip 5-1/2" casing scraper or wireline gauge ring to 1878'.
- 3. Plug #1 (Pictured Cliffs and Fruitland perforations and tops, 2164' 1798'): TIH with tubing and set 5-1/2" CR at 1878'. Pressure test tubing to 1000#. Load the casing with water and circulate the well clean. Pressure test casing to 500#. If casing does not test, then spot or tag subsequent plugs as appropriate. Mix and pump 72 sxs Type III cement, squeeze 58 sxs below CR to fill the PC and FtC perforations, and then leave 14 sxs above CR inside casing to cover the Fruitland top. PUH to 1460'.
- 4. Plug #2 (Kirtland and Ojo Alamo tops, 1460' 1270'): Mix 25 sxs Type III cement (excess due to previous casing leak) and spot a plug inside casing to cover the Kirtland and Ojo Alamo tops. TOH and LD tubing.
- 5. Plug #3 (9-5/8" Surface casing, 143' Surface): Perforate squeeze holes at 143'. Establish circulation out the bradenhead valve with water. Mix and pump approximately 50 sxs Type III cement down the 5-1/2" casing to circulate good cement out bradenhead valve. Shut well in and WOC.
- 6. ND BOP and cut off casing below surface casing flange. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

Recommended:

Operations Engineer

Approved:

managor

**Sundry Required:** 

proved: 71ance

Regulatory

Operations Engineer: Julian Carrillo

Foreman: Joel Lee

Lease Operator: Brooke Hemphill

Specialist: Garry Nelson

Office: 599-4043 Cell: 320-0321 Office: 324-6109 Cell: 320-2490

Office: 324-6109 Cell: 320-2490 Cell: 486-2496 Pager: 324-4341

Cell: 320-2565 Pager: 326-8597

# Newsom B #3


#### Current

### AIN 3207001/3207002

#### **Ballard Pictured Cliffs / Basin Fruitland Coal**

1450' FSL & 990' FWL, Section 8, T-26-N, R-8-W / San Juan County, NM

Long: N 36<sup>29.916</sup> / Lat: W 107<sup>42.636</sup> / API #30-045-05913



TD 2215' PBTD 2182'

## Newsom B #3

## Proposed P:&A

AIN 3207001/3207002

Ballard Pictured Cliffs / Basin Fruitland Coal

1450' FSL & 990' FWL, Section 8, T-26-N, R-8-W / San Juan County, NM

Long: N 36<sup>29.916</sup> / Lat: W 107<sup>42.636</sup> / API #30-045-05913

Today's Date: 10/6/04 Spud: 8/12/1957

PC Completion: 9/4/57 FC Completion: 9/25/01

Elevation: 6315' GL

6323' KB

Isolate holes in casing from 1225' to 1440'; Squeezed with 500

sxs (590 cf) cement. (2001)

(20

12-1/4" hole

9-5/8" 32#, H-40 Casing set @ 93' Cement with 80 sxs (Circulated to Surface)

> Plug #4: 143' - Surface Type III cement, 50 sxs

Plug #2: 1460' - 1270' Type III cement, 25 sxs (extra cement because of previous casing leak)

Ojo Alamo @ 1320'

Kirtland @ 1410'

Fruitland @ 1848'

Pictured Cliffs @ 2063'

7-7/8" hole

TOC @ 1600' (CBL '01)

Cmt Retainer @ 1878'

Fruitland Perforations: 1928' – 2021'

Plug #1: 2164' - 1798'

Type III cement, 72 sxs, 58 sxs below CR and 14 sxs above CR.

Pictured Cliffs Perforations: 2068' – 2164'

5-1/2" 15.5#, J-55 Casing set @ 2205' Cemented with 100 sxs

TD 2215' PBTD 2182'