

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0135  
Expires: November 30, 2000

RECEIVED

2003 APR 30

5. Lease Serial No.

NM - 8007

6. Land, Allottee, or Tribe Name

7. If Unit or CA Agreement Designation

CA NM SW912

8. Well Name and No.

Grigsby Federal #2-7

9. API Well No.

30-045-21507

10. Field and Pool, or Exploratory Area

Basin Dakota

11. County or Parish, State

San Juan, NM

**SUNDRY NOTICES AND REPORTS ON WELLS**  
Do not use this form for proposals to drill or to re-enter an  
abandoned well. Use Form 3160-3 (APD) for such proposals.

**SUBMIT IN TRIPLICATE- Other Instructions on the reverse side**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Chaparral Energy LLC

3a. Address

701 Cedar Lake Blvd  
Oklahoma City, OK 73114

3b. Phone No. (include area code)

(405) 478-8770

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1000' FSL & 1640' FWL  
Unit Letter 'N', Sec. 7-25N-10W, NMPM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent  
☐ Subsequent Report  
☒ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize ☐ Deepen ☐ Production (Start/Resume) ☐ Water Shut-off  
☐ Altering Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity  
☐ Casing Repair ☐ New Construction ☐ Recomplete ☐ Other  
☐ Change Plans ☒ Plug and abandon ☐ Temporarily Abandon  
☐ Convert to Injection ☐ Plug back ☐ Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will be performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Set CIPB @ 5075'.

Plug #1 5075'-4927', 13 sx

Plug #2 2379'-2224', 12 sx

Plug #3 1514'-1126', 30 sx

Plug #4 670'-440', 22 sx

Perforate @ 286' and establish circulation out surface casinghead

Plug #5 286'-surface, 128 sx

Cut off surface and production casing and top off w/8 sx cement. Install marker. Cut off rig anchors. Well P&A.

14. I hereby certify that the foregoing is true and correct.

Name (Printed/ Typed)

Leigh Kuykendall

Title

Engineering Tech

Signature

Leigh Kuykendall

Date

4/28/03

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

ACCEPTED FOR RECORD

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOCDF

APPROVED FOR RECORD