

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004- 0135
Expires: July 31, 1996

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other Instructions on the reverse side

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

Devon Energy Production Co. L.P. Attn: Kenny Rhoades

3a. Address

1751 Highway 511 Navajo Dam, NM 87419

3b. Phone No. (include area code)

(505)320-6310

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1120' FSL & 670' FWL SW 1/4, SW 1/4, Sec. 13, T 31N R. 7W

Latitude

Longitude


12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/ Resume)	<input type="checkbox"/> Water Shut-off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Zonal Isolation
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required susequnet reports shqll be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in anew interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

On 3/14/2003 work commenced to isolate Lewis formation before fracture stimulation.

1. Set CIBP to isolate existing completions
2. Shoot 4 squeeze holes @ 4750' and 4 holes @ 4590'
3. Squeeze w/ 100 sx (21 bbls) "B"
4. Shoot 4 squeeze holes @ 4490'
5. Squeeze holes w/ 50 sx (11 bbls) same slurry



RECEIVED
2003 APR 15 PM 1:48
070 Farmington, NM

14. I hereby certify that the foregoing is true and correct. Name (Printed/ Typed) Kenny Rhoades		Title Company Representative
Signature		Date 4-2-03
THIS SPACE FOR FEDERAL OR STATE OFFICE USE		
Approved by	Title	Date APR 28 2003
Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOCD