Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office *	Energy, Minerals and Natural Resources	Revised March 25, 1999
<u>DISTRICT I</u>		<u>/</u>
1625 N. French Dr., Hobbs, NM 88240	OIL CONSERVATION DIVISION	WELL API NO.
DISTRICT II	1220 South St. Francis Drive	30-045-32723
1301 W. Grand Ave., Artesia, MM 87210	Santa Fe, NM 87505	5. Indicate Type of Lease
DISTRICT III	·	STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410	0 10 20 20	
DISTRICT IV	18 19 (0 2) 33	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		34332
	S AND REPORTS ON WELLS	
	/Do a fight 2 a all	
(DO NOT USE THIS FORM FOR PROP	OSALS TO DRILL OR TO DEEPEN OF THE PARTY TO	
A DIFFERENT RESERVOIR. USE "AI	PPLICATION FOR PERMIT (FORM, COLLEGO DICH	7. Lease Name or Unit Agreement Name
PROPOSALS.)	- On of	<u> </u>
Type of Well:	(C)	ALBERDING 03
OIL GAS		[
WELL WELL X	OTHER PC 45 To The	
	at the	<u> </u>
2. Name of Operator		8. Well No.
PATINA SAN JUAN, INC.		#7
3. Address of Operator		9. Pool name or Wildcat
5802 HIGHWAY 64, FARM	IINGTON, NEW MEXICO 87401	BASIN DAKOTA/BLANCO MESA VERDE
4. Well Location		
Unit Letter G: 1857'	Feet From The NORTH Line and 2302'	Feet From The EAST Line
Section 3	Township 31N Range 13W	NMPM County SAN JUAN
Section		
	10. Elevatior (Show whether DR, RKB, RT, C	iπ, θ(C.)
5779' GR		
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION	ON TO:	SUBSEQUENT REPORT OF:
		oodeach kei okt of .
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIA	AL WORK ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMMEN	ICE DRILLING OPNS. PLUG & ABANDONMENT
PULL OR ALTER CASING	MULTIPLE CASING	TEST & CEMENT JOB
FULL OR ALTER CASING		1231 & CEMENT JOB
	COMPLETION	0-4.4.4/01/ 0
OTHER:	OTHER:	Set 4-1/2" Casing X
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any		
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed worky SEE NOSE 1100. To maniple completions. Attach well-order diagram of proposed completion of recompletion.		
2/16/2005 PIL coping grow 8 run 116 its of 4 1/2" 11 6# LT8C coping to land @ 4900!		
2/16/2005 RU casing crew & run 116 jts of 4-1/2", 11.6# LT&C casing to land @ 4890'		
Cement 1st Stage w/60 bbl mud w/100 cfm/bbl, 20 bbl chemical wash ahead. Cement w/190 sx lead		
@ 12 ppg, 215 sx tail @ 13 ppg & displace w/30 bbl KCL & 45 bbl mud. Plug down @15:00 hrs.		
Had full return	ns, float held. Pressure up to 1600 psi to set packe	er & pr up to 2900 psi to open DV tool.
Cement 2nd Stage w/30 bbl spacer ahead, cement w/290 sx lead @ 11.5 ppg & 200 sx tail @ 12 ppg.		
Plug down @ 17:00 hrs. Close DV tool, had full returns. Circ 28 bbl good cement off DV tool from		
	irc 50 bbl good cement on 2nd Stage. ND BOP &	•
,		
I have by a satisfy the at the information of any	a in two and a small of a the first of any law and also and the	-tr
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
1V2 . X 9 a 1.	1.7.	
SIGNATURE COULD	TITLE PRODUCTI	ON ANALYST DATE 16-Feb-05
1	-	
TYPE OR PRINT NAME KAY S. ECKSTEIN TELEPHONE NO. (505) 632-8056		
(This space for State Use)	1 HATING	SUPERVISOR DISTRICT # 3 EB 2 2 200
APPROVED BY		
CONDITIONS OF ADDDOVAL IF ANY		
CONDITIONS OF APPROVAL, IF ANY:		