In Lieu of Form 3160

UNITED STATES DEDARTMENT OF INTEDIOR

III 0 7 2011

FORM APPROVED

and Log form.)

(June 199	0)	AND MANAGEMENT	0 / 2011	Budget Bureau No 1004-0135 Expires. March 31, 1993		
Do not u	SUNDRY NOTICE AND se this form for proposals to drill or to deepen o TO DRILL" for perm	REPORTS ON WELLS Bureau of L r reentry to a different reservoir Use "APPL		Lease Designation and Serial No. NMSF-078772 If Indian, Allottee or Tribe Name		
	SUBMIT IN 1	RIPLICATE RECEIVE	7.	If Unit or CA, Agreement Designation Rosa Unit		
1.	Type of Well Oil Well X Gas Well Other	RECEIVE		Well Name and No Rosa Unit #355		
2	Name of Operator WILLIAMS PRODUCTION COMPANY	OIL CONS. DIV. DIST.	9. 3 (N) 9.	API Well No 30-045-30192		
3.	Address and Telephone No PO Box 640 Aztec, NM 87410-0640	OF 85 45 41	10.	Field and Pool, or Exploratory Area Basin Fruttland Coal		
4.	Location of Well (Footage, Sec, T, R, M, or Survey Description) 1967 FNL & 1960 FEL SW/4 NE/4 Sec 33, T32N, R6W			County or Parish, State San Juan, New Mexico		
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
	TYPE OF SUBMISSION TYPE			N		
	Notice of Intent X Subsequent Report	Abandonment Recompletion Plugging Back Casing Repair		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off		
ΒP	Final Abandonment	Altering Casing X Other <u>Bradenhead Repair</u>	Dispose	Conversion to Injection Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)		

- 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
 - 5/31/2011 MIRU Hurricane #12. POOH W/98 JTS TBG SN AND 1 JT MA ALL TESTED YELLOW TAG. GIH WITH RTBP AND SET AT 2665'. ND BOP TO INSPECT PROD. CSG. AND HEAD FOUND EXTREEM CORROSION (+- 12' DOWN).
 - 6/1/2011 DIG OUT CELLAR AND REMOVE WELL HEAD. FILL PRODUCTION CSG WITH WATER. CUT OFF AND REMOVE WELLHEAD.
 - 6/2/2011 LOOSENED JT AT 38" POOH WITH DAMAGED 7 " CSG AND REPLACE WITH NEW JT 7" 20# SCREW INTO EXISTING CSG AND TORQUE. PICK UP 10000 OVER WT TO BE SURE THREADS WERE MADE UP GOOD, HELD. RUN 3/4" PVC PIPE TO 40' DOWN ANNULUS OF 7" 20# PRODUCTION CSG RU BJ AND CIIRCULATE TO SURFACE WITH 2 BBLS CLASS C NEAT NO ADDITIVES SET SLIPS ON PRODUCTION CSG.
 - 6/3/2011 GIH WITH TBG CLEAN SAND OFF OF RTBP CIRCULATE CLEAN LATCH RTBP @2665' POOH LAY DOWN RTBP; GIH W/MULE SHOE 1 JT MA 2 7/8" 6.5#EUE 8RD TBG , 1.78 F-NPL @3073',98JTS 2 7/8"EUE 8RD 6.5# J-55 TBG LAND W/EOT @3121'. RDMO

14.	I hereby certify that the foregoing is true and correct Signed Ben Mitchell	Title <u>Regulatory Specialist</u>	Date 7/6/2011	KEEPTED FOR ECONON
	(This space for Federal or State office use)			
	Approved by	Title		DateJUL 1 1 2011
	Conditions of approval, if any:			PARAMICTON FIELD OFFICE

Title 18 U.S.C Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

- 6/17/11 Talked with Charlie Perrin @OCD about no casing pressure test. He gave verbal approval to test Braden Head for communication and pending no communication could continue to flow well.
- 6/28/11 Braden Head test finished with no communication evident. Engineer will schedule MIT test for well.