Submit One Copy To Appropriate District Office	State of New Me		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natu	ral Resources	January 20, 2011 WELL API NO.
<u>District II</u> 1301 W Grand Ave., Artesia, NM 88210			30-031-20613'
District III	rict III 1220 South St. Francis Dr.		5. Indicate Type of Lease  STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM		o. State on the Gas Bease Ivo.	
87505			7 Logo Nome on Unit A recoment Nome
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  PROPOSALS)			7. Lease Name or Unit Agreement Name  Hospah Sand Unit
1. Type of Well: Oil Well Gas Well X Other			8. Well Number 92
2. Name of Operator			9. OGRID Number
Nacogdoches Oil & Gas Inc.			256689
3. Address of Operator 816 North Street, Nacogdoches, TX.	. 75963	·	10. Pool name or Wildcat  Hospah RCVD APR 6'11
4. Well Location		· · · · · · · · · · · · · · · · · · ·	DIL CONS. DIV.
Unit Letter O: 1850' feet from the EAST line and 700' feet from the SOUTH line  DIST. 3			
Section 36 Township 18N Range 9W NMPM County McKinley			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
6957'			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
1	PLUG AND ABANDON	REMEDIAL WOR	
TEMPORARILY ABANDON		<del>_</del>	
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB			<u>—</u>
		_	
OTHER:			
<ul> <li>X All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.</li> <li>X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.</li> </ul>			
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment.			
X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.			
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not			
have to be removed.)			
X All other environmental concerns have been addressed as per OCD rules.			
X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well on lease, all electrical service, poles and lines, not to include primary service company equipment, has been removed from lease and well location.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
1 7 11 1			
			•
SIGNATURE	TITLE_V	P E&P	DATE: <u>4-04-2011</u>
TYPE OR PRINT NAME Mike Allen	E MAII.	mike.allen@nogtx.	com PUONE: 019 240 7420
For State Use Only	E-WIAIL:	mike.alien@nogtx.	.com PHONE: <u>918-260-7620</u>
Conditions of Approval (if any):	A		