

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Tony Delfin
Deputy Cabinet Secretary

David R. Catanach, Division Director
Oil Conservation Division



July 21, 2016

Certified Mail Return Receipt#: 7015 0640 0007 1331 3568

Enervest Operating L.L.C.
Patrick Connelly
1001 Fannin Street
Suite 800
Houston, TX 77002-7002

Re: Well Name Jicarilla Tribal 396 #6, UL C Sec 17 Twn 23N Rge 3W,
API # 30-039-23415

Dear Mr. Connelly:

The 2016 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to provide a course of action to this office before **August 21, 2016** and initiate remedial activity before **October 21, 2016**. Initial Surface Casing psi was 134. Initial Production Casing psi was 84. During the test the Production Casing pressure dropped while Surface Casing was open. The test shows there is direct communication between the casing strings.

A gas analysis and wellbore schematic have been requested. Please submit as soon as possible.

Reference: RBDMS MPK1619357773 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 116.

Sincerely yours,

Brandon Powell
Inspection and Enforcement Supervisor

cc: Jicarilla Oil and Gas Administration
Well File
BLM Farmington

ec. Jicarilla BIA
Jicarilla Oil and Gas Administration